

ASS. REC. BY: Janu

REF: CS3/ASM 22008937/Rqy3


4046
CORRECTION: 2029/JAN

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJM 7435X
at Workshop m/s SZE KANH Automobile
of 10, AMK Highway # 03-17
Insured: ASM
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SJM 7435X Yr Regn: 2009 / JAN
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: MERCEDES BENZ C180K c.c. 1796
Colour: GRGY A/C: Insured / Std / NI / NA
Sp. Reading: 227732 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD2040462A203742
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or
Brake: Order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17
R: _____
BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or -



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 71K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 09/09/22 D.O.L. 15/09/22
Survey held at SZE KANH
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 51K
	ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?

2) _____
Report Format : _____
Lump Sum / I.B.F. : _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	404G

Vehicle Details

Vehicle No.:	SJM7435X
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180K
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	27195231120693
Chassis No.:	WDD2040462A203742
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$37,063.00
Original Registration Date:	15 Jan 2009
First Registration Date:	15 Jan 2009
Transfer Count:	2
Actual ARF Paid:	\$37,063.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	14 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$19,811.00
Total Rebate Amount:	\$19,811.00

The information contained herein is correct as at 18 Sep 2022

OK

Mercedes-Benz C-Class C180K (COE till 10/2028)

Overview

Financial

Accessories

Similar

Research

Photos

Men



Price **\$68,800**

Depreciation \$11,320 /yr

Reg Date 15-Oct-2008
(6yrs 26days COE left)

Mileage 121,312 km (8.7k /yr)

Manufactured 2008

Road Tax \$1,364 /yr

Transmission Auto

Dereg Value \$19,615 as of today (change)

OMV	\$37,066
-----	----------

COE	\$32,279
-----	----------

ARF	\$37,066
-----	----------

Engine Cap	1,796 cc
------------	----------

Power	115.0 kW (154 bhp)
--------------	--------------------

Curb Weight 1,485 kg

No. of Owners	4
---------------	---

Typical of the luxury sedan