REC'D / FILE BY: GQ | REF: CS/CTI22008953/Gvy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / W/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s KIVILE ENTERPRISE

of

Insured: SKU 1638M

Policy No. DMPCSNW00101222101

Claims No. SNM22D204334/C02/KHONGLH

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: $11k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBQ9850R Yr Regn: 22 Jan/2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA AEROX GDR155R c.c 155

Colour White A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH3SG4620KJ066505

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/80-14

R: 150/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or MITAS

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 18/6/2022 D.O.I. 13-09-2022

Survey held at W/S 5PM

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
6/2/23	Submit preli report-revised fig $4612.50 check items $1914

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 6/2/23-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / UPR: