

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO22008957/Uqy3q2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date:	28/09/2022	
			Code	: SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMG 7687G	Veh. Inspected	SMW 8726L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2203223/AGC	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	12/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 116I (A)	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WBA1A12090VV25952	Colour	BLACK	
	Odometer	115878 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
	L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
	R/H Rear Tyre	245/35 R18	GOODYEAR	6 mm	
	L/H Rear Tyre	245/35 R18	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/09/2022	Inspection Date	12/09/2022	
	Survey held at	IMPERIUM AUTOMOTIVE			
		25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				