

A.S.S. REC BY: ToughREF: CS/TM/2208963/Twy3

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS upDate: _____ Person Contacted: James

Vehicle: IN / OUT

Veh No: SH6363XYr Regn: 20/9, Ay

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai WrigC.C. 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 319311

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UWHC851CVK4164975Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wartburg

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 12/9/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/ or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos

Others

Report Format: _____

Lump Sum / L.B.H. (\$) _____

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Jumani
(Masud)

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	10/09/2022
Vehicle Reg. No.:	SH6363X	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	06/08/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU298718	Chassis No:	KMHC851CVKU164975
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,984.60
Miscellaneous Items	11.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,745.60
+ GST 7.00% (\$\$)	192.19
Nett Amount (\$\$)	2,937.79

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH6363X/12/09/2022 12:08**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	de *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	uu *22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de *451.25 FL
4	1		*REAR BUMPER TOW COVER	20.00	0.00	x *98.80 FL
5	1		*REAR BUMPER LOWER CENTRE COVER	20.00	0.00	x *225.00 FL
6	1		*FOG LAMP REAR	20.00	0.00	x *201.50 FL
7	1		*ANTENNA SMARTKEY	20.00	0.00	x *40.50 FL
8	1		*REAR NUMBER PLATE WITH CASING	0.00	0.00	uu *50.00 F
9	1		*REAR BUMPER BEAM	20.00	0.00	? *394.80 FL
10	1		*ADVERTISEMENT LOGO - BUMPER	20.00	0.00	uu *100.00 FL
11	1		*ADVERTISEMENT LOGO - FENDER	20.00	0.00	uu *200.00 FL
12	1		*REVERSE SENSOR	0.00	0.00	uu *180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 2,423.25

- List Item Discount on L Items (S\$) 438.65

Total Parts (S\$) 1,984.60

ComfortDelGro Engineering Pte Ltd/SH6363X/12/09/2022 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350

400.00

2 SPRAYPAINT

New

250

300.00

3 REMOVE / REFIX REVERSE SENSOR

New

50

50.00

Gross Labour Cost (S\$)

750.00

ComfortDelGro Engineering Pte Ltd/SH6363X/12/09/2022 12:08. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Jia 27495747
 WP 12/9/22 CSpm
 2 days
 < b Resurvey after repair
 Tan Jia / Khairul

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 12.09.2022 11:56

Page : 1

m: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC N005529512

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

JUNT CARD NO.

REGN NO.:

SH 6363X

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 12.09.2022 10:15

YR OF MANU.

06.08.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164975

COMPLETION DATE/TIME:

JOB DESCRIPTION


ident Date: 10.09.2022

URE: 3P.10.09.22

IO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

SH 6363X

JU TOKIO

Vehicle No.:

SH 6363X

Service Advisor

Signature/Date

Name of Service Advisor

Date

rned to Service Reception upon collection

To be kept by Security Guard