


ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLK 3818M  
 at Workshop m/s: 200M  
 of \_\_\_\_\_  
 Insured: SLD 88 96R  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLK 3818M Yr Regn: 28/02/20  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA/ Puretech Petrol  
 Make: Peugeot 3008 c.c. 1598  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 25602 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VF3M45GFRKS124939  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/65 R17  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 7 mm R/Bal. 7 mm  
 L/Bal. 7 mm L/Bal. 7 mm  
 D.O.A. 10/09/22 D.O.I. 13/09/22  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear & Frnt.  
 The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: €125k.  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 9 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: 929f  
HTA 42826 Vehicle: IN / OUT

Date / Time Action / Instruction Rep 15k.  
No 2020 model from SG car mart  
3/10/22 4/5 €9000 insured Elin

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I.: (\$ \_\_\_\_\_ )

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  
 : Interview (\$ \_\_\_\_\_ )  
 : Tech. Invs (\$ \_\_\_\_\_ )  
 : Weekend (\$ \_\_\_\_\_ )

Others: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 TOTAL \_\_\_\_\_