

C3/CT.1 22008983/TP43

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Ching (Ysum)
Date: 19.07.2022
Time: 16:41:27
Page: 1
JH

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305523844
REGN NO : SHA2044K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 15.12.2016
DATE/TIME IN : 19.07.2022 15:05
ACCIDENT DATE : 19.07.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	/ de	
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	/ dis	
0003 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	Xun	
0004 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	Xun	
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ nec	803 20% 642.40
0006 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	/ nec	SN 50

SUB-TOTAL : 1,130.72

JOB NATURE

0000 PB	PANEL BEATING	300.00	280	642.40
0001 SP	SPRAYPAINT CHARGE	300.00	350	50
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30	890
0003 20-05	ADVERTISEMENT STICKER-BUMPER	50.00	30 890	1582.40
0004 20-05	ADVERTISEMENT STICKER-FENDER	200.00	/ nec	41591200

Tanphi
97445744
20/7/22 1630
L/s 2 days swp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: