



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009000/Uny3q2	
			Date: 28/09/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 9105K	Veh. Inspected	SGF 7037J
	Policy No.	D22MTPV01005110	Coverage (\$)	0.00
	Claim No.	CMTD2203241/RUC	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	13/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN X-TRAIL (A)	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JN1JANT32Z0001595	Colour	GREY
	Odometer	139969 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R18	PIRELLI	6 mm
	L/H Front Tyre	235/60 R18	PIRELLI	6 mm
	R/H Rear Tyre	235/60 R18	PIRELLI	6 mm
	L/H Rear Tyre	235/60 R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/09/2022	Inspection Date	14/09/2022
	Survey held at	SIANG HUI MOTOR WORKS BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	