



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                              |                                                                                                                                        |                                                                                                        |                                                             |            |
|------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN: HO WINNIE |                                                                                                                                        |                                                                                                        | Ref: CS/ASM22009005/Uvy3m4<br>Date: 19/10/2022<br>Code: ASM |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                              |                                                                                                                                        |                                                                                                        |                                                             |            |
|                                                                                                | Insured Veh.                                                                                                                           | FBS 3931U                                                                                              | Veh. Inspected                                              | SJW 9939T  |
|                                                                                                | Policy No.                                                                                                                             | AN3200370                                                                                              | Coverage (\$)                                               | 0.00       |
|                                                                                                | Claim No.                                                                                                                              | S2M04AU8                                                                                               | Excess (\$)                                                 | 0.00       |
|                                                                                                | Assign From                                                                                                                            | HO WINNIE                                                                                              | Assign Date                                                 | 13/09/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                  |                                                                                                                                        |                                                                                                        |                                                             |            |
|                                                                                                | Make & Model                                                                                                                           | MERCEDES BENZ C180 (A)                                                                                 | c.c                                                         | 1595       |
|                                                                                                | Engine No.                                                                                                                             | HIDDEN                                                                                                 | Year of Reg.                                                | 2019       |
|                                                                                                | Chassis No.                                                                                                                            | WDD2050402R477560                                                                                      | Colour                                                      | SILVER     |
|                                                                                                | Odometer                                                                                                                               | 40984 KM                                                                                               | Steering                                                    | IN ORDER   |
|                                                                                                | Brakes                                                                                                                                 | IN ORDER                                                                                               | Modification                                                | SPORTS RIM |
|                                                                                                | General                                                                                                                                | GOOD                                                                                                   |                                                             |            |
| <b>3. Conditions of Tyres</b>                                                                  |                                                                                                                                        |                                                                                                        |                                                             |            |
|                                                                                                |                                                                                                                                        | Size                                                                                                   | Make                                                        | Balance    |
|                                                                                                | R/H Front Tyre                                                                                                                         | 245/35 ZR19                                                                                            | FALKEN                                                      | 6 mm       |
|                                                                                                | L/H Front Tyre                                                                                                                         | 245/35 ZR19                                                                                            | FALKEN                                                      | 6 mm       |
|                                                                                                | R/H Rear Tyre                                                                                                                          | 245/35 ZR19                                                                                            | FALKEN                                                      | 6 mm       |
|                                                                                                | L/H Rear Tyre                                                                                                                          | 245/35 ZR19                                                                                            | FALKEN                                                      | 6 mm       |
| <b>4. Description of Damages</b>                                                               |                                                                                                                                        |                                                                                                        |                                                             |            |
|                                                                                                | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.<br>DAMAGES SEE DETAILS.                                                         |                                                                                                        |                                                             |            |
| <b>5. General Information</b>                                                                  |                                                                                                                                        |                                                                                                        |                                                             |            |
|                                                                                                | Accident Date                                                                                                                          | 10/09/2022                                                                                             | Inspection Date                                             | 15/09/2022 |
|                                                                                                | Survey held at                                                                                                                         | GLATT AUTO KIT PTE LTD<br>NO. 1 KAKI BUKIT AVENUE 6<br>#01-53 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                                                             |            |
| <b>5a. Remarks</b>                                                                             |                                                                                                                                        |                                                                                                        |                                                             |            |
|                                                                                                | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                        |                                                             |            |
| <b>5b. Estimate Days of Repair</b>                                                             |                                                                                                                                        |                                                                                                        |                                                             |            |
|                                                                                                | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                        | 3 Working Days                                              |            |