

ASS. REC. BY: Form

REF: CS3/ASM22009025/Rvy3

7262

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 4P 87790

at Workshop m/s HIAP LEK

of 160 SIN MINS DR #05-12

Insured: ASM

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 77K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 4P 87790 Yr Regn: 2018 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI CANTER FEB 21 ER c.c. 2998

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 175334 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB 21 6A 25 195

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/85R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front R/Bal. 7 mm Rear R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 26/08/22 D.O.I. 26/09/22

Survey held at HIAP LEK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 59K</u>
	<u>ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (5K - 6K) / 6 days</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.R. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

- Add Fee:
- : Site Insp (\$ _____)
 - : Interview (\$ _____)
 - : Tech. Invs (\$ _____)
 - : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS	
Photos	
Others	
TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	726Z
Vehicle No.:	YP8779D
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Sep 2022
Vehicle Make:	mitsubishi
Vehicle Model:	CANTER FEB21ER4SDEN (CBU)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	4P10D18833
Chassis No.:	FEB21EA25195
Maximum Power Output:	-
Open Market Value:	\$35,480.00
Original Registration Date:	22 Jun 2018
First Registration Date:	22 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$1,774.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	21 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,902.00
COE Rebate Amount:	\$17,151.00
Total Rebate Amount:	\$17,151.00

The information contained herein is correct as at 27 Sep 2022

OK

Mitsubishi Fuso Canter FEB21

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)



Envision your ideal vehicle.

Price	\$77,800	Lifespan	12-Jun-2038
Depreciation	\$13,620 /yr View models with similar depre	Reg Date	13-Jun-2018 (5yrs 8mths 16days COE left)
Mileage	N.A.	Manufactured	2018
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$8,275 as of today (change)	Fuel Type	Diesel
COE	\$14,486	OMV	\$35,480
Engine Cap	2,998 cc	ARF	\$1,774
Curb Weight	2,500 kg	No. of Owners	1