

A.S.S. REC. BY:

REF:

CS3/ASM22009030/RVY3

4730

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNA 2888Xat Workshop n/s KUM CHENof 160, SIN MMR 28 AUG 08Insured: SLX 1437Z ASM

Policy No. _____


Claims No. S2M04AY3

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 58K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 2888X Yr Regn: 2015 JANType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HARRIER ELG 2.0A c.c. 1986Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 89538 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 28U600028158Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/60R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/09/22D.O.I. 14/09/22

Survey held at

KUM CHEN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S & REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

REPAIR LIMIT - 30K16/9/22 ESTIMATE RANGE OF REPAIR/no. of days - (9K-10K) / 8 days

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) 16/9/22-typist

Report Format: _____

Lump Sum / I.B.R. (%) _____

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	473D
Vehicle No.:	SNA2888X
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 A
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	3ZRB463809
Chassis No.:	ZSU600028158
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$25,258.00
Original Registration Date:	06 Jan 2015
First Registration Date:	06 Jan 2015
Transfer Count:	2
Actual ARF Paid:	\$17,362.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2025
PARF Rebate Amount:	\$10,417.00
COE Expiry Date:	05 Jan 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$73,900.00
COE Rebate Amount:	\$16,811.00
Total Rebate Amount:	\$27,228.00

The Information contained herein is correct as at 15 Sep 2022

OK

Toyota Harrier 2.0A Elegance

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$58,800****Depreciation** ⓘ

\$21,700 /yr

[View models with similar depre](#)**Reg Date**

06-Jan-2015

(2yrs 3mths 21days COE left)

Mileage

80,000 km (10.4k /yr)

Manufactured ⓘ

2014

Road Tax ⓘ

\$1,196 /yr

Transmission

Auto

Dereg Value ⓘ

\$27,210 as of today (change)

OMV ⓘ

\$25,258

COE ⓘ

\$73,900

ARF ⓘ

\$17,362

Engine Cap

1,986 cc

Power

111.0 kW (148 bhp)

Curb Weight ⓘ

1,580 kg

No. of Owners ⓘ

3

Type of Vehicle

SUV