



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                                                                                |                                         |                 |                                                            |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|-----------------|------------------------------------------------------------|--|
| ERGO INSURANCE PTE LTD<br>8 TEMASEK BOULEVARD, #04-01 SUNTEC<br>TOWER THREE SINGAPORE 038988                                                                                                                                                     |                                         |                 | Ref: CS3/EGI22009037/Twy3<br>Date: 14/09/2022<br>Code: EGI |  |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>                                                                                                                                                                                              |                                         |                 |                                                            |  |
| Insured Veh.                                                                                                                                                                                                                                     | YP 6143B                                | Veh. Inspected  | XE 7733L                                                   |  |
| Policy No.                                                                                                                                                                                                                                       |                                         | Coverage (\$)   | 0.00                                                       |  |
| Claim No.                                                                                                                                                                                                                                        | CDMCG21000753                           | Excess (\$)     | 0.00                                                       |  |
| Assign From                                                                                                                                                                                                                                      | PAULINE SOH                             | Assign Date     | 14/09/2022                                                 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                                                                                    |                                         |                 |                                                            |  |
| Make & Model                                                                                                                                                                                                                                     |                                         | c.c             | 0                                                          |  |
| Engine No.                                                                                                                                                                                                                                       | HIDDEN                                  | Year of Reg.    |                                                            |  |
| Chassis No.                                                                                                                                                                                                                                      |                                         | Colour          |                                                            |  |
| Odometer                                                                                                                                                                                                                                         | -                                       | Steering        |                                                            |  |
| Brakes                                                                                                                                                                                                                                           |                                         | Modification    |                                                            |  |
| General                                                                                                                                                                                                                                          |                                         |                 |                                                            |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                                                                                    |                                         |                 |                                                            |  |
|                                                                                                                                                                                                                                                  | Size                                    | Make            | Balance                                                    |  |
| R/H Front Tyre                                                                                                                                                                                                                                   |                                         |                 | mm                                                         |  |
| L/H Front Tyre                                                                                                                                                                                                                                   |                                         |                 | mm                                                         |  |
| R/H Rear Tyre                                                                                                                                                                                                                                    |                                         |                 | mm                                                         |  |
| L/H Rear Tyre                                                                                                                                                                                                                                    |                                         |                 | mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                                                                                                                                 |                                         |                 |                                                            |  |
|                                                                                                                                                                                                                                                  |                                         |                 |                                                            |  |
| <b>5. General Information</b>                                                                                                                                                                                                                    |                                         |                 |                                                            |  |
| Accident Date                                                                                                                                                                                                                                    | 20/04/2021                              | Inspection Date | 14/09/2022                                                 |  |
| Survey held at                                                                                                                                                                                                                                   | 68 Kaki Bukit Avenue 6, #01-22 ARK @ KB |                 |                                                            |  |
| Repairer                                                                                                                                                                                                                                         | ZOOM AUTOWERKS PTE LTD                  |                 |                                                            |  |
| <b>5a. Remarks</b>                                                                                                                                                                                                                               |                                         |                 |                                                            |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                                         |                 |                                                            |  |