



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM22009039/Kpa3q2 Date: 10/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4872H	Veh. Inspected	GBH 5249B	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M04AL3	Excess (\$)	0.00	
Assign From		Assign Date	14/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ VITO 114 CDI (A)	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDF44760323351809	Colour	RED	
Odometer	134883 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MINNELL	8 mm	
L/H Front Tyre	215/60 R16	MINNELL	8 mm	
R/H Rear Tyre	215/60 R16	MINNELL	9 mm	
L/H Rear Tyre	215/60 R16	MINNELL	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/09/2022	Inspection Date	14/09/2022	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	