

ASS. REC BY: Toupin

REF: CS/CT/27009240/TVY3

**ASSIGNMENT**

2023 Aug  
2008 Dec

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated cost: \_\_\_\_\_

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SMW 4511R

Policy No. DMPCSNW00263252101

Claims No. SNM22D206527/C02/KAHLEONG

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vch: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 411K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKT42089 Yr Regn: 2008 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota V115 C.C. 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 30815 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MROSS ZEE106\*127180

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:  

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/9/2022 D.O.I. 15/9/22

Survey held at Bigfoot

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction
8/12/22	Lump Sum \$3100 confirmed by email (red 29,333.78, 90%)

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? 2) 9/12/22-typist

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Report Format: Merimen

Lump Sum / L.B. (\$) \$3100

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
S + RS. SI	_____
Photos	_____
Others	_____
TOTAL	_____

## Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875  
Tel: 93290237 Email: claims\_rar@bifrostauto.com

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Date of ReSurvey: \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : SKT 4208G  
Made : Toyota  
Model : Corolla Altis 1.6 Auto  
Chassis No : \_\_\_\_\_

### \* AGREED Cost Of Repair and Repair Day/s with SJE \*

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 582.89	\$ <i>de</i> 582.89
2	Front Bumper Side Retainer RH	1	\$ 52.50	\$ X 52.50
3	Front Bumper Side Retainer LH	1	\$ 52.50	\$ X 52.50
4	Front Bumper Fog Lamp LH	1	\$ 183.60	\$ X 183.60
5	Front Bumper Fog Lamp Garnish LH	1	\$ 91.20	\$ X 91.20
6	Front Bumper Reinforcement	1	\$ 395.20	\$ X 395.20
7	Front Bumper Lower Grille	1	\$ 198.50	\$ X 198.50
8	Front Headlamp Assembly RH	1	\$ 528.60	\$ X 528.60
9	Front Headlamp Assembly LH	1	\$ 528.60	\$ X 528.60
10	Front Grille	1	\$ 316.60	\$ X 316.60
11	Front Grille Emblem	1	\$ 65.00	\$ X 65.00
12	Front Support Panel	1	\$ 591.60	\$ X 591.60
13	Front Bonnet	1	\$ 845.10	\$ X 845.10
14	Front Bonnet Hinge RH	1	\$ 62.00	\$ X 62.00
15	Front Bonnet Hinge LH	1	\$ 62.00	\$ X 62.00
16	Front Fender LH	1	\$ 498.10	\$ <i>de</i> 498.10
17	Front Fender Emblem LH	1	\$ 55.90	\$ <i>de</i> 55.90
18	Front Fender Inner Cowling LH	1	\$ 145.60	\$ X 145.60
19	Front Shock Absorber LH	1	\$ 430.40	\$ X 430.40
20	Front Knuckle Arm LH	1	\$ 427.20	\$ X 427.20
21	Front Knuckle Arm Bearing LH	1	\$ 203.90	\$ X 203.90
22	Front Lower Arm LH	1	\$ 381.60	\$ X 381.60
23	Front Tie Rod LH	1	\$ 206.80	\$ X 206.80
24	Steering Rack And Pinion	1	\$ 1,970.40	\$ X 1,970.40
25	Front Drive Shaft LH	1	\$ 1,842.60	\$ X 1,842.60
26	Rocker Panel Garnish LH	1	\$ 765.10	\$ <i>de</i> 765.10
27	Front Door LH	1	\$ 1,102.80	\$ <i>de</i> 1,102.80
28	Front Door Side Mirror LH	1	\$ 599.80	\$ X ? 599.80
29	Front Door Upper Hinge LH	1	\$ 80.30	\$ X 80.30
30	Front Door Lower Hinge LH	1	\$ 80.30	\$ X 80.30
31	Front Door Checker LH	1	\$ 62.10	\$ X 62.10
32	Front Door Inner Lock LH	1	\$ 324.60	\$ X 324.60

33	Front Door Inner Trim Board LH	1	\$	668.70	\$ X	668.70
34	Front Door Weatherstrip LH	1	\$	164.40	\$ X	164.40
35	Front Door Window Glass Regulator LH	1	\$	263.20	\$ X	263.20
36	Front Door Window Glass Regulator Motor LH	1	\$	657.40	\$ X	657.40
37	Front Door Window Outer Moulding LH	1	\$	142.60	\$ X	142.60
38	Rear Fender LH	1	\$	982.40	\$ X	982.40
39	Rear Fender Inner Cowling LH	1	\$	110.45	\$ X	110.45
40	Rear Fender Air Vent LH	1	\$	138.00	\$ X	138.00
41	Rear Windscreen Glass Outer Moulding	1	\$	123.30	\$ ✓	123.30
42	Rear Door LH	1	\$	1,212.70	\$ X	1,212.70
43	Rear Door Inner Lock LH	1	\$	482.40	\$ X	482.40
44	Rear Door Black Tape LH	1	\$	44.00	\$ X	44.00
45	Rear Door Glass Outer Moulding LH	1	\$	113.10	\$ X	113.10
46	Rear Door Outer Handle LH	1	\$	172.50	\$ X	172.50
47	Rear Door Weatherstrip LH	1	\$	173.50	\$ X	173.50
48	Rear Door Inner Trim Board LH	1	\$	796.70	\$ X	796.70
49	Rear Door Power Window Regulator LH	1	\$	214.30	\$ X	214.30
50	Rear Door Power Window Motor LH	1	\$	619.40	\$ ✓	619.40
51	Rear Door Upper Hinge LH	1	\$	91.30	\$ X	91.30
52	Rear Door Lower Hinge LH	1	\$	91.00	\$ X	91.00
53	Rear Shock Absorber LH	1	\$	220.30	\$ X	220.30
54	Rear Wheel Hub Bearing LH	1	\$	365.90	\$ X	365.90
55	Rear Axle	1	\$	3,444.50	\$ X	3,444.50
56	Rear Bumper	1	\$	495.20	\$ X	495.20
57	Rear Bumper Side Retainer RH	1	\$	60.00	\$ X	60.00
58	Rear Bumper Side Retainer LH	1	\$	60.00	\$ X	60.00
59	Rear Bumper Reflector LH	1	\$	60.40	\$ X	60.40
60	Rear End Panel	1	\$	670.00	\$ X	670.00
61	Rear End Panel Top Garnish	1	\$	241.90	\$ X	241.90
62	Rear Taillamp Assembly LH	1	\$	494.00	\$ X	494.00
63	Rear Bootlid	1	\$	793.20	\$ X	793.20
64	Rear Bootlid Taillamp LH	1	\$	353.30	\$ X	353.30
65	Rear Bootlid Emblem	1	\$	61.60	\$ X	61.60
66	Rear Bootlid "Corolla" Emblem	1	\$	48.30	\$ X	48.30
67	Rear Bootlid "Altis" Emblem	1	\$	43.50	\$ X	43.50
68	Rear Bootlid "1.6" Emblem	1	\$	38.70	\$ X	38.70
69	Rear Bootlid Lock	1	\$	399.50	\$ X	399.50
					Parts Sub Total :	\$ 28,845.04
					25% Discount	\$ 7,211.26
					<b>PARTS TOTAL :</b>	<b>\$ 21,633.78</b>

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 50.00	\$ X 50.00
2	Front Bumper Clips - Set	1	\$ 50.00	\$ 30441 ✓ 50.00
3	Front Grille Clips - Set	1	\$ 50.00	\$ X 50.00

4	Front Fender Inner Cowling Clips LH - Set	1	\$ 50.00	\$ X	50.00
5	Front Door Inner Trim Board Clips LH - Set	1	\$ 50.00	\$ X	50.00
6	Rear Door Inner Trim Board Clips LH - Set	1	\$ 50.00	\$ X	50.00
7	Rocker Panel Garnish Clips LH - Set	1	\$ 50.00	\$ <i>30.00</i>	50.00
8	Rear Fender Inner Cowling Clips LH - Set	1	\$ 50.00	\$ X	50.00
9	Rear Bumper Clips - Set	1	\$ 50.00	\$ X	50.00
10	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ X	50.00
11	Front Bonnet Sealant	1	\$ 150.00	\$ X	150.00
12	Front Fender LH Sealant	1	\$ 150.00	\$ X	150.00
13	Front Support Panel Sealant	1	\$ 150.00	\$ X	150.00
14	Front Door LH Sealant	1	\$ 150.00	\$ X	150.00
15	Rear Door LH Sealant	1	\$ 150.00	\$ X	150.00
16	Rear Fender LH Sealant	1	\$ 150.00	\$ X	150.00
17	Rear Bootlid Sealant	1	\$ 150.00	\$ X	150.00
18	Rear End Panel Sealant	1	\$ 150.00	\$ X	150.00
19	Rear Windscreen Glass Sealant	1	\$ 150.00	\$ X	150.00
20	Radiator Coolant	1	\$ 100.00	\$ X	100.00
21	Front Wheel Rim LH	1	\$ 550.00	\$ <i>cut</i>	550.00
22	Front Tyre LH	1	\$ 350.00	\$ X	350.00
23	Rear Wheel Rim LH	1	\$ 550.00	\$ X	550.00
24	Rear Tyre LH	1	\$ 350.00	\$ X	350.00
25	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ X	250.00
<b>SPECIAL NETT TOTAL :</b>				<b>\$</b>	<b>4,000.00</b>

Nos.	LABOUR	TOTAL \$
1	To Panel Beat, Remove & Refix Parts	\$ <i>500</i> 2,000.00
2	To Spray Paint Affected Areas	\$ <i>600</i> 1,800.00
3	Wiring & Bulb Check	\$ X 100.00
4	To Transfer Bootlid Mechanism	\$ X 150.00
5	To Transfer Front Door LH Mechanism	\$ <i>60</i> 150.00
6	To Transfer Rear Door LH Mechanism	\$ X 150.00
7	To Remove & Refix Rear Bootlid Camera	\$ X 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ X 120.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
10	To apply anti rust on affected parts	\$ <i>30</i> 150.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X 150.00
12	To Remove & Refix Rear Windscreen Glass	\$ X 150.00
13	To Conduct Water Leak Test	\$ X 100.00
14	To Remove & Refix Front Undercarriage	\$ X 250.00
15	To Remove & Refix Rear Undercarriage	\$ X 500.00
16	To Conduct Four Wheel Alignment	\$ <i>680</i> 150.00
17	To Remove & Refix Petrol Tank to facilitate repairs	\$ X 250.00
<b>LABOUR TOTAL :</b>		<b>\$ 6,800.00</b>

PARTS TOTAL :	\$	21,633.78
SPECIAL NETT TOTAL :	\$	4,000.00
LABOUR TOTAL :	\$	6,800.00
<b>GRAND TOTAL :</b>	<b>\$</b>	<b>32,433.78</b>

Taufik 97495749  
 WP' 15/9/77 @ 440pm  
 L/S Resury after work  
 Taufik C/Thantoun  
 4 days

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	642C
Vehicle Details	
Vehicle No.:	SKT4208G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	3ZZ4813444
Chassis No.:	MR053ZEE106124180
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	22 Dec 2008
First Registration Date:	22 Dec 2008
Transfer Count:	4
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$3,291.00
<b>Total Rebate Amount:</b>	<b>\$3,291.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Sep 2022

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission .....	12/09/2022 18:34 (SGT)
Reported by .....	Driver
Date of Accident .....	11/09/2022 04:25 (SGT)
Exact Location of Accident .....	Clemenceau Ave, Clemenceau Bridge, Singapore
Additional Location Information .....	-
Country/State of Loss .....	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKT4208G

#### INSURED/POLICYHOLDER

Is company? .....	Yes
Name Of Registered Owner .....	LCH Car Rental Pte Ltd
Company Reg No .....	201601642C
Email Address .....	lchcarrental@gmail.com
Mobile Phone No .....	(Phone) +65-86853446
Alternative Phone No .....	-

#### VEHICLE PARTICULARS

Manufacturer .....	Toyota
Model .....	Corolla
Variant .....	ALTIS 1.6 AUTO
Exact purpose for which vehicle was being used at time of accident .....	Private hire
Are you claiming under your own insurance policy for repair to your vehicle? .....	No - Claiming third party
Vehicle Category .....	Private hire
Transmission .....	Auto
CC .....	1598

#### INSURANCE COMPANY

Name of Insurance Company .....	Income Insurance Limited
Policy Number / Cover Note Number .....	5120265380-01

#### DRIVER

Name of Driver .....	Ang Geok Beng
NRIC No .....	S7038932J
Date Of Birth .....	07/11/1970
Occupation .....	Outdoor

Date Of Driving Pass .....	11/10/2005
Driving experience .....	16 YEARS AND 11 MONTHS
Gender .....	Male
Mobile Number .....	(Phone) +65-82555178
Alt. Phone Number .....	-
Email Address .....	anggeokbeng1122@gmail.com
Address .....	Block 503 Hougang Avenue 8
Address complement .....	#10-722
Postcode .....	530503
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Hirer
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Change/cross lane
Weather Conditions .....	Clear
Road Surface .....	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	Yes
Was any injured conveyed to hospital by ambulance? .....	No
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

PASSENGER 1

Name .....	Ah Boy
Gender .....	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	Yes
Police Station Name .....	Hougang Neighbourhood Police Centre
Police Station Phone No .....	(Phone) +65-18004890999
Alt. Police Station Phone No .....	(Fax) +65-63128989
Police Station Address .....	60 Hougang Ave 9 Singapore 538775
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

CIRCUMSTANCES OF ACCIDENT

Refer to Police Report

ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SMW4511R
Vehicle Manufacturer .....	Porsche
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	White
Vehicle Category .....	Private hire
Name of Driver .....	-
Contact Number .....	-
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-

### INJURED PERSONS DETAILS

#### INJURED 1


Name of injured person .....	Ang Geok Beng
Gender .....	Male
Phone No .....	(Phone) +65-82555178
Address .....	-
Address Complement .....	-
Post Code .....	-
Approximate Age Years Old .....	-
Injuries Sustained .....	Refer to Police Report.
Injured person in which vehicle? .....	SKT4208G
Were seat belts worn? .....	Yes
Was this injured conveyed to hospital by ambulance? .....	No

Describe Circumstance of the Accident

Refer to Police Report.

Declaration

I/We declare that the particulars are true in every respect.

  
Reg No: 201601642C  
Policyholder's Signature / Date & Time



  
12/09/22  
Actual Driver's Signature (if driver is not the policyholder)  
Date & Time

  
Tham Chi En  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC / ID card)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**6. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
 Reg No: 2016018420  
 Policyholder's Signature / Date & Time

  
 12/09/2022  
 Actual Driver's Signature (if driver is not the policyholder) / Date & Time

  
 Witnessed by Reporting Centre Personnel  
 (Name as in NRIC/ID card)

Sketch Plan



v1.0 2022



**SINGAPORE  
POLICE FORCE**



T202209122137

Police Station Of Origin:  
Hougang N.P.C  
63 Hougang Avenue 9 SINGAPORE 539775  
Tel No: 1800-4890999

Report No: T202209122137

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 12/09/2022 15:05	Vide Report No.:	Station Diary No. 80
--	------------------	-------------------------

**Informant's Particulars**

Name of Informant: ANG GEOK BENG		Address APT BLK 503 HOUGANG AVENUE 8 #10-722 SINGAPORE 530503	
ID Type / ID No. NRIC NO / S7038932J		Contact No. Home/Office	Mobile: 92555176
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 51	Date of Birth: 07/11/1970	Type of Informant: Driver
Race: Chinese	Language: Chinese		Institution / School Name:
Occupation: FOOD STALL OWNER	Driving Licence Information: Class: 3		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/09/2022 04:25	Type of Location: Straight Road
Location: CLEMENCEAU AVENUE				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: Two Way	Traffic Control:		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKT4206G	Car				Slightly Damaged	1
SMW4511R	Car				Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T20220912/2137

Police Station Of Origin  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 536775  
Tel No. 1800-4890999

Report No. T20220912/2137

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	ANG GEOK BENG	ID No.	S7038932J
Related Vehicle	SKT4208G (Car)	Contact No.	8255517B
Hospital/Clinic	INTEMEDICAL KOWAN	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On 11/09/2022 at about 0425hrs, I was driving my vehicle (SKT4208G) along Clemenceau Avenue. I was driving along lane 1 of Clemenceau Avenue when a vehicle (SMW4511R) wanted to change to lane 1. The driver of SMW4511R did not check his blind spot and collided into the side of my vehicle.

The driver of SMW4511R did not stop his vehicle and drove off. I followed his car to Havelock Road when the traffic light was red eventually, he came to stop. I wanted to exchange particulars but he refused to give me his particulars. He took down my number and informed that he will be contacting me.

I would like to state that he did not contact me till today 12/09/2022. I have visited a clinic Intemedical Kowan and was given 5 days of MC dated from 12/09/2022 to 16/09/2022. I do have the footage of the incident. No traffic police or ambulance was at scene.

POLICE REPORT



SINGAPORE  
POLICE FORCE



T20220122137

Police Station Of Origin  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 536775  
Tel No: 1800-4899999

Page 1  
Report No: T20220122137

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:  
F  
SGT 1 CHERLEINE TOH YU OI

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
12/09/2022 15:05

Officer In Charge Of Case:  
TP / AEIT /  
SR STAFF SGT FAHRUL RAZI BIN SUHAIME  
Contact No.: 65470000

Classification Of Case:

NP168