

Ass. Rec. BY: \_\_\_\_\_ REP: \_\_\_\_\_

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: Smu2946T Yr Regn: 2016 June  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Nissan X-Trail c.c. 1997  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 111478 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JN1JANT3220001992  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 235/60R18  
 R: 235/60R18

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. ob mm R/Bal. ob mm  
 L/Bal. ob mm L/Bal. ob mm  
 D.O.A. \_\_\_\_\_ D.O.I. 15/09/22  
 Survey held at Detail Lab

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Front a/s, u/c  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Action</u>
	LS \$6450, 5 days. (Red \$11948, 65%)
	MV :
	PV :
	Nett :
	<u>251 I</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) 10/02 Typist

Days Of Repair: 5  
 Resurvey No. of Trip: 1

Survey Fee:	
Transport:	
Photos	
Others	

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Inve (\$)

Report Format: MER-TP