

ASS. REC. BY:

Prme

REF:

CS3/11122009057/Rny3

5467

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FU 1111A

at Workshop m/s KM PLUS MOTOR P/L

of 61, WOODMANNS RD PK 89 #01-14 @ 69

Insured: 1112

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Sal. or Market Value: 14K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FU 1111A Yr Regiv: 2021 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: YAMAHA NMAX 155 ABS CVT c.c 155

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 47002 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH 3565680 MK 086264

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or _____

Brake: Order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 110/70-13

R: 140/80-13

BS / DUN / EXNOVA / GY / FS / LIZA / MTC / OHTSU / PIR / SUMI /

TOYO / YOKO or - _____

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 10/09/22 D.O.I. 19/09/22

Survey held at KM PLUS

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 6.5K</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____ S + RS _____ SI
 Photos _____
 Others _____

1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format: _____
 Lump Sum / I.C.P. (%) _____

KM Plus Motor Pte Ltd

61 Woodlands Industrial Park E9
#01-14 E9 Premium, Singapore 757047

13 September 2022

REG NO.: FU 1111 A
MAKE/MODEL: YAMAHA NMAX

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
2	Side fork tube assy <i>X</i>	\$ 1,960.00
1	Fork under bracket <i>X</i>	\$ 190.00
1	Headlamp <i>X</i>	\$ 800.00
1	Side mirror -LH <i>2.500 ✓</i>	\$ 120.00
1	Handle bar <i>?</i>	\$ 180.00
1	Handle bar balancer <i>500 ✓</i>	\$ 50.00
1	Hand grip (1 set) <i>X</i>	\$ 80.00
1	Brake lever <i>500 ✓</i>	\$ 58.00
1	Lower belly panel <i>500 ✓</i>	\$ 250.00
1	Footstep panel -LH <i>?</i>	\$ 165.00
1	Rear taillamp <i>X</i>	\$ 285.00
1	Rear fender <i>?</i>	\$ 155.00
1	Rear footrest -LH <i>X</i>	\$ 85.00
1	Drove belt cover <i>500 ✓</i>	\$ 250.00
1	Air filter box cover <i>500 ✓</i>	\$ 220.00
1	Main stand <i>X</i>	\$ 145.00
1	Side stand <i>X</i>	\$ 95.00
1	Rear fender <i>X</i>	\$ 148.00
1	Fairing cover (1 set) <i>X</i>	\$ 1,350.00
		\$ 6,586.00
		Less 10% \$ 658.60
		\$ 5,927.40

Resul
Hp 90010068
3 days
L/S
19/09/22 @ 1510
Resy after repair

S/N	DESCRIPTION	AMT(\$)
1	Number plate (1 set) <i>X</i>	\$ 28.00
1	Rear box bracket <i>bl ✓</i>	\$ 250.00 (50)
2	Fork oils <i>X</i>	\$ 30.00
2	Fork oil seals <i>X</i>	\$ 56.00
1	Steering cone (1 set) <i>X</i>	\$ 120.00
1	"NMAX" emblem <i>re ✓</i>	\$ 60.00 30
		\$ 544.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting \$
- To display damaged part(s) during resurvey \$
- Parts prices are subject to confirmation \$
- Third party survey is on a "Without Prejudice" basis \$
- No illegal modification(s) is allowed \$
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company \$

Acknowledged by Repairer
Signature:
Date:

S/N	LABOUR CHARGES	AMT(\$)
1	To provide towing service.	\$ 50.00 <i>X</i>
2	To check wiring and reset headlamp focusing	\$ 80.00 <i>X</i>
3	To provide labour.	\$ 380.00 250
		\$ 510.00

GRAND TOTAL : \$ 6,981.40

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	546J
Vehicle No.:	FU1111A
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2022
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX 155 ABS CVT
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	G3L8E0606190
Chassis No.:	MH3SG5680MK086264
Maximum Power Output:	-
Open Market Value:	\$2,737.00
Original Registration Date:	02 Jul 2021
First Registration Date:	02 Jul 2021
Transfer Count:	1
Actual ARF Paid:	\$411.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	01 Jul 2031
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$8,501.00
COE Rebate Amount:	\$7,464.00
Total Rebate Amount:	\$7,464.00

The information contained herein is correct as at 20 Sep 2022

OK

Yamaha Nmax 155

Listing Type	Free Ad
Brand	Yamaha
Model	Yamaha Nmax 155
Engine Capacity	155cc
Classification	Class 2B
Registration Date	23/07/2021
COE Expiry Date	22/07/2031 (8yrs 10mths 2days COE left)
Mileage	-
No. of owners	1
Type of Vehicle	Scooters

SGD **\$14688**