



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22009060/Svy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675		Date:	30/11/2022
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 1924A	Veh. Inspected	SLC 7459G
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/056	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	14/09/2022
2. Vehicle Particulars & Condition			
Make & Model	KIA FORTE K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAFX411MG5601839	Colour	BLACK
Odometer	116378 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	5 mm
L/H Rear Tyre	205/55 R16	KUMHO	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/09/2022	Inspection Date	12/10/2022
Survey held at	KAN FOOK SING MOTOR WORKSHOP BLK.8 JTC DEFU INDUSTRIAL CITY #04-29 DEFU SOUTH STREET 1 SINGAPORE 533758		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	