



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22004846/Kvy3e2-1	
			Date: 23/09/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMY 6416J	Veh. Inspected	XE 2548M	
Policy No.	D22MTPV01003686	Coverage (\$)	0.00	
Claim No.	CMTD2201735/THE	Excess (\$)	0.00	
Assign From	THELMA CHOO	Assign Date	14/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CWB5E	c.c	10837	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JNCM1F1D5HU015241	Colour	YELLOW	
Odometer	210600 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	FALKEN	3 mm	
L/H Front Tyre	295/80 R22.5	FALKEN	3 mm	
R/H Rear Tyre	295/80 R22.5 (D)	WEST LAKE	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	WEST LAKE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/05/2022	Inspection Date	25/05/2022	
Survey held at	160 Sin Ming Drive #06-06 Sin Ming AutoCity			
Repairer	OMEGA AUTO PL			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	