



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM22009082/Apa3q2 Date: 21/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 9149D	Veh. Inspected	SDD 228S
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M04APB	Excess (\$)	0.00
	Assign From		Assign Date	09/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD2050422R062954	Colour	SILVER
	Odometer	101622 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	GOODYEAR	6 mm
	L/H Front Tyre	225/45 R18	GOODYEAR	6 mm
	R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
	L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/09/2022	Inspection Date	19/09/2022
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	