

ASS. REG. BY: Form


REF: CS/AIS 22009089/Rny3

2512

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLT 4442J
at Workshop m/s HC AUTO
of 160, SIN MINH DL # 05-09
Insured: AS
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLT 4442J Yr Regit: 2017 / 04
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: HONDA VEZEL 1.5X CVT c.c. 1496
Colour: BLUE A/C: Insured / Std / NI / NA
Sp. Reading: 084576 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RU11227158
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Knoder / Jammed / Leaked / Burnt or _____
Brake: Knoder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 215/55R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 71K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 13/09/22 D.O.I. 15/09/22
Survey held at HC AUTO
Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or
Repair N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 43K</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

1) _____ Date/Time, File Return to?
2) _____
Report Format: _____
Lump Sum / I.B.P. (\$) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 13 / 09 / 2022

ESTIMATE	COSTS	OF REPAIR
----------	-------	-----------

Mr. Wong Yung Yeow

C/o 160 Sin Ming Drive
#05-09 Sin Ming Auto City
Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SLT 4442 J - Honda Vezel 1.5X CVT
Accident date : 13 / 09 / 2022

	Quantity	Descriptions	Amount (S\$)
	1	1 pc tail gate <i>bt</i>	\$ 1,450.00
	2	1 pc tail gate weather strip <i>new</i>	\$ 185.00
	3	1 pc tail gate inner lock <i>X</i>	\$ 310.00
	4	1 pc tail gate inner trim <i>cm</i>	\$ 325.00
	5	1 pc tail gate Honda logo <i>new X</i>	\$ 53.00
	6	1 pc tail gate ' VEZEL ' emblem <i>new</i>	\$ 55.00
	7	1 pc tail gate ' I-VTEC ' emblem <i>new</i>	\$ 58.00
	8	1 pc n/s tail gate reflector <i>X</i>	\$ 350.00
	9	1 pc n/s tail lamp <i>X</i>	\$ 650.00
	10	1 pc rear bumper fascia <i>de</i>	\$ 1,120.00
	11	1 pc n/s rear bumper side cover <i>de</i>	\$ 470.00
	12	1 pc n/s rear bumper bracket <i>X</i>	\$ 70.00
	13	1 pc n/s rear bumper side retainer <i>X</i>	\$ 64.00
	14	1 pc n/s rear bumper reflector <i>cm</i>	\$ 144.00
	15	1 pc rear bumper center cover (accessories) <i>scr</i>	\$ 850.00
	16	1 pc rear bumper lower garnish <i>de</i>	\$ 422.60
	17	1 pc n/s rear fender <i>repair</i>	\$ 1,080.00
	18	1 pc n/s rear fender inner garnish <i>cm</i>	\$ 320.00
	19	1 pc n/s rear fender wheel arch garnish <i>cm</i>	\$ 150.00
	20	1 pc rear end panel <i>repair</i>	\$ 620.00
	21	1 pc rear end panel inner garnish <i>cm</i>	\$ 216.00
	22	1 pc rear windscreen glass molding <i>new</i>	\$ 150.00
			\$ 9,112.60
		Less 20 %	\$ 1,822.52
		Balance C/FD	\$ 7,290.08

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

	Balance B/FD (SLT 4442 J)	\$ 7,290.08
23	1 pc rear windscreen inner seal <i>nw</i>	\$ 60.00 sn } 60
24	1 pc rear windscreen inner gum <i>nw</i>	\$ 60.00 sn }
25	1 pc rear floor panel <i>repair</i>	\$ 1,275.00 sn <i>X</i>
26	1 pc tools box <i>com</i>	\$ 250.00 sn <i>X</i>
27	1 pc rear spare tyre board <i>2.0L X</i>	\$ 280.00 sn <i>X</i>
28	1 set reverse sensor <i>nw</i>	\$ 350.00 sn <i>200</i>
		\$ 9,565.08
	Labour charges	\$ 1,800.00 <i>1500/1500</i>
	To putty and spray painting	\$ 1,400.00 <i>900</i>
	To check wiring	\$ 120.00 <i>X</i>
	To transfer tail gate	\$ 120.00 <i>60</i>
	To check wheel alignment	\$ 120.00 <i>X</i>
	To re-seal anti rust	\$ 150.00 <i>40</i>
	Refix reverse sensor	\$ 120.00 <i>40</i>
	Remove and refix rear windscreen glass	\$ 220.00 <i>120</i>
	Remove and refix cushion seat, garnish, carpet & etc.	\$ 250.00 <i>60</i>
	Plus : 7% GST	\$ 13,865.08
	Sub_Total	\$ 970.56
		\$ 14,835.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
7 days
L/S
15/09/22 @ 1250
Resury after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/09/2022 13:53 (SGT)
Reported by	Driver
Date of Accident	13/09/2022 12:20 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	FILTER LANE TOWARDS JALAN ANAK BUKIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT4442J
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	WONG YUNG YEOW
NRIC No	SXXXX251Z
Email Address	yungyeoww@gmail.com
Mobile Phone No	(Phone) +65-96447768
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezele
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5104045664-03

DRIVER

Name of Driver	BAN JIN HONG
NRIC No	SXXXX480Z
Date Of Birth	20/02/1995
Occupation	Indoor

Driving experience	5 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97704888
Alt. Phone Number	-
Email Address	banjinhong@gmail.com
Address	BLK 475B UPPER SERANGOON CRESCENT
Address complement	#12-535
Postcode	532475
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Friend
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	SHIH YIN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE SEE ATTACHED SKETCH PLANS.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ1732U
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-

Vehicle Category

Name of Driver

NRIC No

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

Private car

NEO JIE MING

SXXXX573Z

(Phone) +65-83826999

-

-

-

-

-

-

-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;


(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstances of the Accident

On 13/09/2022 at about 12:30hrs, while I stopped my motor vehicle A 8L74442 J along PIE filter lane to Jalan Anak Bukit to give way to on coming vehicle from my right. Suddenly I felt an impact from behind. I realised that was a motor vehicle B 8KQ 1732 U hit me from behind. I'm lodging this report to claim against the insurer of 8KQ 1732 U.

- Claim OD
 Claim Third Party
 Claim OD/TP at other workshop
 Reporting Only

Please forward a copy of my efile accident report to:

My workshop : H C Auto Dte Ltd 

Email address : hcauto@stingnet.com.sg

Myself email : yungyeauw@gmail.com

Note: Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own Insurer for more information.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 251Z

Vehicle Details

Vehicle No.: SLT4442J
Vehicle to be Exported: No
Intended Deregistration Date: 18 Sep 2022
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: L15B4427760
Chassis No.: RU11227758
Maximum Power Output: 96.0kW (128 bhp)
Open Market Value: \$21,115.00
Original Registration Date: 30 Oct 2017
First Registration Date: 30 Oct 2017
Transfer Count: 0
Actual ARF Paid: \$11,561.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Oct 2027
PARF Rebate Amount: \$8,670.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$36,001.00
COE Rebate Amount: \$18,406.00
Total Rebate Amount: \$27,076.00

The information contained herein is correct as at 18 Sep 2022

OK

Honda Vezel 1.5A X

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)

Established since 2002



CAR WORLD



Price

\$69,800

Depreciation

\$12,850 /yr

[View models with similar depre](#)

Reg Date

31-Aug-2017

(4yrs 11mths 12days COE left)

Mileage

63,800 km (12.6k /yr)

Manufactured

2016

Road Tax

\$682 /yr

Transmission

Auto

Dereg Value

\$30,999 as of today (change)

OMV

\$21,655

COE

\$45,201

ARF

\$12,317

Engine Cap

1,496 cc

Power

96.0 kW (128 bhp)

Curb Weight

1,190 kg

No. of Owners

2