ASS. RECABY: STOR J CS/CTI)	1009093/Kg u3 1"			
ASSI	GMMENT			
From: Date:	Veh No: SMX 60554 Yr Regn; 211121			
Estimated Cost:	Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /			
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or			
To Inspect Vehicle No:	Make: RMW X/ cc 1499			
at Workshop m/s	Colour S/UP A/C: Insured / Std / NI / NA			
of	Sp.Reading 07368 T/Radio: Insured / Std / NI / NA			
Insured:	Eng/No:			
Policy No.	CNO: WBA32AA0605553433			
Claims No.	Gen. Cond: Good Fair / Poor / Burnt			
Sum Insured: Excess:	Steering:  norder/Jammed/Leaked/Burnt or			
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or			
Make of Veh.	Modi: Nii / SiRim / STD A/Rim or			
	Tyre Size: F: 015/6081/			
(Policy Condition)	, R: 1/			
Remark: The veh had commenced its N/S O/S	BS ( OUD) EXNOVA ( GY / FS ( LIZA / MIC / OHTSU / PIR / SUMI /			
repair at the time of inspection.	TOYO / YOKO or			
Bal. or Market Value:	Front Rear			
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. L/ mm , R/Bal. L/ mm			
GIA / PR Seen: Consistent? : Yes or No	UBal. UBal. UBal. UBal.			
Est Repairs: 5 days Res.: Yes or No	D.O.A. 6977 D. C. D.O.I. 21977			
Lum Sum: % 3 Val.: Yes or No	Survey held at PPACMING			
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rea / O/S / N/S / U/C / Rooftop or			
Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.			
Date: Person Contacted:	The U/C I Chassis frame I Body Structure another services			
Date / Time   Action / Instruction /				
- 191V 151A				
Steve finalised final fig \$9319.29, 5	days (Red \$5483.25, 37%)			
- Covernment of the first of th	<u>aaja (1.153 45 156.126, 61 76)</u>			
4				
nin Consta	Days Of Repair: 5			
Oale/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: Survey Fee:			
1) 27/10 Typist : Final Report	Transportation:			
Date/Time, File Return to?	ee: : Site Insp (\$)_s+Rssi			
2)	: Interview (\$ ) Photos			
MER-TP	: Tech, Invs (\$) Others			
Repair officer;	: Weel and (*)			
Lung Sum (1.8.1: (\$ 9319.29 )	TOTAL			

BMW pealer

# Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-X Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	:	b1	63	225
Date Estimated	:	06/	09/2	022
Prepared By	:	Yap	Mee	Key

ESTIMATE REPAIR FOR -WORLD F PTE LTD 47 TOH TUCK PLACE TOH TUCK GARDEN

40000 ACCOUNT -

Cash Sales - Service

Singapore

SINGAPORE 596822

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

WBA32AA0605S53433 SMX6055Y

DESCRIPTION

REAR SILENCER

BOOTLID

RUBBER MOUNTING

TAILPIPE TRIM BRIGHT CHROME

21/01/2021

X1 sDrive18i

20192

			_
DESCRIPTION To replace tailgate, rear bumper carrier and rear bumper. 1/2 m/(	2125	1780	VALUE 3,400.00
To respray taigate and rear bumper.	1972	梅	2,076.00
To replace rear exhaust silencer including alignment system and conduct check for leak.		1	531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.		168	177.00
To check electrical.		168	177.00
To replace rear windscreen glass.		545	574.00
To supply and install rear windscreen solar film.		504	531.00
To conduct water leak tests.		71	75.00
To carry out body cavity preservation. (Per panel).		112	118.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.		5 94	531.00
Sundries.			150.00
	Total Labour 1:	8	,340.00

QTY

3

1

PRIC

18.15

125.55

1,298.95

1 1,108.15



VALUE

54.45

125.55

1,108.15

1,298.95

# Performance Motors Limited

k sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road sime Darby Performance Centre singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 (AfterSales) (Motorrad) Fax. 64796601 64796624



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 63225

nate Estimated

: 06/09/2022

prepared By

Yap Mee Key

Page No. : 2 of 5

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

20192

SMX6055Y

WBA32AA0605S53433

21/01/2021

X1 sDrive18i

VALUE PRIC DESCRIPTION 226.95 REAR BUMPER TRIM PANEL (X LINE) / (VI) 226.95 1 523.75 523.75 1 RR BUMPER CARRIER 907.80 907.80 1 REAR BUMPER PANEL PRIMED REAR BUMPER MIDDLE TRIM PANEL (PDC) / (VI) 266.90 266.90 1 31.00 10 3.10 1 DRC PLUG IN NUT 37.70 37.70 1 REAR BUMPER TOWING EYE COVER X 815.55 1 815.55 REAR WINDOW (ESG) 169.85 169.85 **BOOTLID SEALING** 26.15 26.15 (DG) CLEANER R1 (100ML) (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) / MC 263.10 2 131.55

5,855.85 Total Parts

Steve (LKK) WL PL 21/9/22, 10.30= MBL L

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1 8,340.00 : Parts 5,855.85 Labour 2 0.00 Excess 0.00 Total GST @ 7% 993.71

Grand Total

15,189.56

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

SP0X22970002 / Performance Motors Limited ENTRY DATE & TIME: 07/09/2022 18:01 (SGT) SUBMITTED BY: Inthiran all Thurasamy VERSION: 1 (07/09/2022 18:01 (SGT))



# **SINGAPORE ACCIDENT STATEMENT**

#### IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver.

3. Information provided must be as truthful and accurate as possible, Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate.

policy tiability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

07/09/2022 18:01 (SGT) Date of Submission Driver Reported by 06/09/2022 14:20 (SGT) Date of Accident **Exact Location of Accident** Singapore Additional Location Information **Bukit Timah Road** Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

BMW

No - Claiming third party

SMX6055Y Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner World Pte. Ltd. Company Reg No 2XXXXX842D Email Address fujiyoshiyukako@gmail.com Mobile Phone No (Phone) +65-90285430 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Model X1 Variant Exact purpose for which vehicle was being used at time of Private use accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Private car Transmission Auto CC 1499

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd Policy Number / Cover Note Number

DRIVER

Name of Driver Yukako Fujiyoshi Passport No/FIN GXXXX930R Date Of Birth 07/09/1973 Occupation Indoor

Accident report SP0X22970002

Page 1 of 21



29/10/2018 Date Of Driving Pass 3 YEARS AND 11 MONTHS Driving experience Male Gender (Phone) +65-90285430 Mobile Number Alt. Phone Number fujiyoshiyukako@gmail.com **Email Address** 47 Toh Tuk Place Address Address complement 596822 Postcode No Is the driver the policyholder? Director If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident Clear Weather Conditions Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident No Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION No Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT Refer to Sketch Plan. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? **DETAILS OF OTHER VEHICLE PROPERTY 1 GBG2960E** Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver Ganesh

(Phone) +65-90069903

**CS** CamScanner

Contact Number

Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

China Taiping Insurance (Singapore) Pte. Ltd.

#### SKETCH PLAN

## IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orderspended MOTORS LIMITED 303 Alexandra Road

Sime Derby Performance Centre Sh 190610 109961 72L . . . 13010. , Sales)

63183111 (Alarsales)

Policyholder's Signa Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

