



# COMFORTDELGRO ENGINEERING PTE LTD

SHS-KLV

## REPAIR ESTIMATE

LKK-

DATE: 14.09.2022  
 MODEL: Toyota Prius  
 VEHICLE NO.: SH 8507K

INSURANCE: CHINA TAIPING (L/S)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$503.04 <i>RK</i>
	Rear Bumper Re-Inforcement	1		\$378.32 <i>?</i>
	Rear Bumper Lower Cover	1		\$654.96 <i>de</i>
	Rear Bumper Clips	10	\$2.20	\$22.00 <i>ue</i>
	Rear Bumper Tow Cover	1		\$82.70 <i>de</i>
	<b>SUB TOTAL</b>			<b>\$1,641.02</b>
	<b>LESS 25%</b>			<b>\$389.58</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,168.74</b>
	Reverse Sensor	1		\$135.70 <i>am</i>
	Rear Bumper Mat	1		\$50.00 <i>x</i>
	Rear Bumper Adv.Sticker	1		\$50.00 <i>int</i>
	Rear Fender Adv.Sticker RH / LH	2	\$100.00	\$200.00 <i>ue</i>
	<b>NETT TOTAL</b>			<b>\$435.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$400.00 <i>550</i>
	Spray Painting Charge			\$300.00 <i>250</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$820.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,424.44</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tanfah 97495749*  
*WP 14/9/22 04pm*  
*L/S Resurvey after repair*  
*2 days*  
*Tanfah C/Insurance*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Date/Time: 14.09.2022 14:26 Page : 1

Job: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4775372

JC No: 305529909

OWNER  
 IS COMFORT TRANSPORTATION PTE LTD  
 OWNER NO. 7010045  
 ADDRESS 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 (R) 65508755 (O)  
 (P)  
 IDENTIFICATION CARD NO.


REGN NO. SH 8507K	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)	DATE/TIME IN 14.09.2022 10:55
YR OF MANU. 20.09.2017	TARGET DATE
CHASSIS CODE JTDKB3FU003564079	COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 13.09.2022  
 DURE: 3P 13.09.2022

IO LABOR CODE  
 010 PB

DESCRIPTION  
 PANEL BEATING-SH 8507K-TP



RECEIVED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

Signature Slip

Exit Pass

Vehicle No.: SH 8507K LIMTS

Vehicle No.: SH 8507K

\_\_\_\_\_  
 Service Advisor

\_\_\_\_\_  
 Signature/Date

\_\_\_\_\_  
 Name of Service Advisor

\_\_\_\_\_  
 Date

Returned to Service Reception upon collection

To be kept by Security Guard