

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305529909  
Date : 16.09.2022

## FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SH 8507K

Date of Accident : 13.09.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBG2908H
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges (include advertisement stickers etc,if any) \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c.) Lumpsum Repair (if applicable)
 

Total for Lumpsum repair cost after Less: <u>20%</u>	\$1,250.00
<b>Final Lumpsum Repair cost</b>	<b>\$1,250.00</b>
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : TAUFIKH  
Date : 02/11/2022

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_