

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s THIAM HENG HUAT

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S

Bal. or Market Value: \$36k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: - days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKA8044K

Yr Regn: 01 Apr/2011

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA JAZZ 1.3 c.c. 1339

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 151738 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMGE68509S238931 *

Gen. Cond: ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/R or

Tyre Size: F: 205/45R16

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 16-09-2022

Survey held at W/S 11:30AM

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop orThe ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimate give later

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

S + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long. Cdn. / MPB: