Ass. Pd. By: | REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJZ928/R Yr Regn: 2018, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Nissan Note c.c 1198

Colour Red. A/C: Insured / Std / NI / NA

Sp.Reading 123974 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNITAAE12Z0980174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/65R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	19/09/22.

Survey held at Mirage.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front O/S, U/C.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP MSLG.
	MV :
	PV :
	Nett :
	665G

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____) ☐ : Interview ($ _____) ☐ : Tech. Inve ($ _____)

Survey Fee: _____

Transportation: _____ S + RS. ___ SI

Photos _____

Others _____

Report Format: _____