

ASS. REC. BY:

REF:

CS/CT122009170/Rvc

961K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: SMX 57194at Workshop m/s My CAR CONSULTANT P/Lof 60, JARAN LAM HONG #105-21Insured: SLM 5376Y CTIPolicy No. DMPCSNW00265002100Claims No. SNM22D206455/C02/IRENE

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 158K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMX 57194 Yr Regn: 2021 / JanType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA NOAH HYBRID 1.8X c.c. 1797Colour: MAXIM A/C: Insured / Std / NI / NASp. Reading: 155157 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR800428316

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZAFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 09/09/22 D.O.I. 19/09/22Survey held at My CAR CONSULTANTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 97K

27/1/23 Lump Sum \$3850 confirmed by email (red 7411.49, 65%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 31/1/23-typist

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / L.B. / \$3850

Estimation

Date: 15/9/2022

Vehicle: SMX5719Y

Make / Model: TOYOTA NOAH

Chassis No: CT

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER <i>de</i>	1	\$ 798.20	\$ 798.20
2	REAR BUMPER SIDE RETAINER <i>X</i>	2	\$ 171.45	\$ 324.40
3	TAILGATE <i>hu</i>	1	\$ 2,110.25	\$ 2,110.25
4	TAILGATE INNER TRIM <i>X</i>	1	\$ 589.00	\$ 589.00
5	TAILGATE "HYBRID SYNERGY DRIVE LOGO" <i>ne</i>	1	\$ 141.10	\$ 141.10
6	TAILGATE WEATHERSTRIPE <i>ne</i>	1	\$ 391.05	\$ 391.05
7	TAILGATE LOCK <i>X</i>	1	\$ 512.00	\$ 512.00
8	TAILGATE WINDSCREEN MOULDING (SET) <i>ne</i>	1	\$ 387.00	\$ 387.00
9	TAILGATE DETECTOR <i>X</i>	1	\$ 287.00	\$ 287.00
10	TAILGATE BUZZER <i>X</i>	1	\$ 198.00	\$ 198.00
11	REAR END PANEL <i>ht</i>	1	\$ 689.20	\$ 689.20
12	REAR END PANEL TOP GARNISH <i>cm</i>	1	\$ 391.45	\$ 391.45
13	REAR FLOOR PANEL <i>X</i>	1	\$ 2,489.00	\$ 2,489.00
14	REAR FLOOR PANEL TOP BOARD SET <i>X</i>	1	\$ 1,241.00	\$ 1,241.00
	TOTAL PART			\$ 10,548.65
	LIST DOWN	25%		\$ 2,637.16
	AFTER LIST DOWN			\$ 7,911.49
	S/N			
1	REAR NUMBER PLATE <i>X</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER REVERSE SENSOR <i>X</i>	1	\$ 220.00	\$ 220.00
3	REAR BUMPER CLIP <i>ne</i>	1	\$ 50.00	\$ 50.00
4	TAILGATE WINDSCREEN SEALANT <i>ne</i>	1	\$ 80.00	\$ 80.00
5	TAILGATE WINDSCREEN INNER SEAL <i>ne</i>	1	\$ 80.00	\$ 80.00
7	TAILGATE INNER TRIM BOARD CLIPS SET <i>ne</i>	1	\$ 50.00	\$ 50.00
8	REAR END PANEL SEALANT <i>ne</i>	1	\$ 120.00	\$ 120.00
9	REAR END PANEL TOP GARNISH CLIP <i>ne</i>	1	\$ 30.00	\$ 30.00
	TOTAL SPECIAL NETT			\$ 680.00
	Labour to:			
1	REMOVE AND REFIT REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
2	REMOVE AND REFIT REAR SEAT, UPHOLTERY	1	\$ 300.00	\$ 300.00
3	REMOVE AND REFIT REAR REVERSE SENSOR	1	\$ 120.00	\$ 120.00
4	REMOVE AND REFIT TAILGATE MECHANISM	1	\$ 150.00	\$ 150.00
5	TO CHECK ELECTRICAL WIRING	1	\$ 200.00	\$ 200.00
6	TUFF COAT	1	\$ 150.00	\$ 150.00
7	PANEL BEATING ON AFFECTED AREA	1	\$ 800.00	\$ 800.00
8	SPRAY ON AFFECTED AREA	1	\$ 800.00	\$ 800.00
				\$ 2,670.00

30
60
30
40
20
120
X
40
60
X
40
600
600

		Parts Replacement Amount	\$ 8,591.49
		Total Amount for Labour	\$ 2,670.00
		Total Amount	\$ 11,261.49

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Passul

Hp 90010068

6 & days

L/S

19/09/22 P1620

Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/09/2022 13:26 (SGT)
Reported by	Driver
Date of Accident	09/09/2022 14:30 (SGT)
Exact Location of Accident	Lentor Ave, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX5719Y
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	LUMENS AUTO PTE LTD
Company Reg No	2XXXXX961K
Email Address	kokhow.tay@lumens.sg
Mobile Phone No	(Phone) +65-92327447
Alternative Phone No	(Office) +65-87781765

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Noah
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1797

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number	21-MM000793-R00

DRIVER

Name of Driver	YUSOF BIN ABDUL GHANI
NRIC No	SXXXX137F
Date Of Birth	28/11/1965
Occupation	Outdoor

Driving Pass
Experience
Driver
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

01/02/1994
28 YEARS AND 7 MONTHS
Male
(Phone) +65-92327447
-
kokhow.tay@lumens.sg
220 TAMPINES STREET 24 #04-114
-

520220
No
Hirer
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Raining
Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? Yes
Was any injured conveyed to hospital by ambulance? No
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
Translator's name -
Translator's ID -
Translator's phone number -
Translator's email -
Original language used in the statement -

PASSENGER 1

Name UNKNOWN
Gender Female

PASSENGER 2

Name UNKNOWN
Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
Police Station Name Traffic Police
Police Station Phone No (Phone) +65-65470000
Alt. Police Station Phone No (Fax) +65-65474900
Police Station Address 10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON 09/09/2022 AT ABOUT 1430HRS, I WAS DRIVING VEHICLE A ALONG LENTOR AVENUE TOWARDS JUNCTIONS OF YISHUN AVENUE 2. AS VEHICLE A WAS STATIONARY AT THE TRAFFIC LIGHT JUNCTION ON THE FOURTH LANE. WHILE VEHICLE A WAS WAITING FOR THE GREEN LIGHT, VEHICLE A FELT A STRONG IMPACT FROM THE REAR AND REALISED VEHICLE B HAD REAR ENDED VEHICLE A. NOBODY WAS INJURED AT THE TIME OF ACCIDENT.

ATTACHMENT(S)

Ident photos available for attachment?
Were any video captured by Car Camera?

Yes
Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM5376Y
Vehicle Manufacturer	Volkswagen
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	ADAM
Address	(Phone) +65-87920213
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	NUR HANNANI BINTE YUSOF
Gender	Female
Phone No	(Phone) +65-92278763
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	3DAYS MC
Injured person in which vehicle?	SMX5719Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

INJURED 2

Name of injured person	SAPIAH BTE HAMZAH
Gender	Female
Phone No	(Phone) +65-92278033
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	3DAYS MC
Injured person in which vehicle?	SMX5719Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

09/09/2022. /2000hrs

Witnessed by Reporting Centre Personnel

Sketch Plan



A - SMX5719Y
B - SLM5376Y

Describe Circumstances of the Accident

ON 09/09/2022 AT ABOUT 1430HRS, I WAS DRIVING VEHICLE A ALONG LENTOR AVENUE TOWARDS JUNCTIONS OF YISHUN AVENUE 2. AS VEHICLE A WAS STATIONARY AT THE TRAFFIC LIGHT JUNCTION ON THE FOURTH LANE. WHILE VEHICLE A WAS WAITING FOR THE GREEN LIGHT, VEHICLE A FELT A STRONG IMPACT FROM THE REAR AND REALISED VEHICLE B HAD REAR ENDED VEHICLE A. NOBODY WAS INJURED AT THE TIME OF ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 09/09/2022. 2000hrs

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	961K
Vehicle No.:	SMX5719Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 1.8X CVT
Primary Colour:	Purple
Manufacturing Year:	2019
Engine No.:	2ZR2G40744
Chassis No.:	ZWR800428316
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$34,781.00
Original Registration Date:	20 Jan 2021
First Registration Date:	20 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$25,694.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2031
PARF Rebate Amount:	\$19,270.00
COE Expiry Date:	19 Jan 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,001.00
COE Rebate Amount:	\$40,820.00
Total Rebate Amount:	\$60,090.00

The information contained herein is correct as at 20 Sep 2022

OK

Toyota Noah Hybrid 1.8A X

Overview

Financial

Accessories

Similar

Research

Photos

Map



Our Accreditation:



Price

\$158,800

Depreciation

\$17,440 /yr

[View models with similar depre](#)

Reg Date

28-Jan-2021

(8yrs 4mths 7days COE left)

Mileage

65,000 km (39.5k /yr)

Manufactured

2020

Road Tax

\$974 /yr

Transmission

Auto

Dereg Value

\$61,390 as of today (change)

Fuel Type

Petrol-Electric

COE

\$50,100

OMV

\$35,011

Engine Cap

1,797 cc

ARF

\$26,016

Curb Weight

1,610 kg

Power

100.0 kW (134 bhp)