

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	F	Ref:	CS3/ASM22009193/Tcm4		
	8 SHENTON WAY SINGAPORE 0688	Γ	Date:	23/09/2022		
	ATTN: GARNET LO	DW	(	Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SNE 1497B	Veh. Inspected		SJR 3094X	
	Policy No.	P2469433	Coverage (\$)		0.00	
	Claim No.	S2M04B84	Excess (\$)		0.00	
	Assign From	GARNET LOW	Assign Date		19/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA CAMRY	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	MR053BK4007034607	Colour		SILVER	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	MICHELIN		6 mm	
	L/H Front Tyre	215/55 R17	MICHELIN		6 mm	
	R/H Rear Tyre	215/55 R17	MICHELIN		6 mm	
	L/H Rear Tyre	215/55 R17	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.					
5.	. General Information					
	Accident Date	16/09/2022	Inspect Date / Ti	ime	19/09/2022 ( 05:08 PM )	
	Survey held at	D'S GRAFFITI CONCEPTS PTE	LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	ia. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$14,000-\$16,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days					

Report Ref No. CS3/ASM22009193/Tcm4

Inspected By

MOHAMAD TAUFIKH

h

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser