

Service Request Details

Claim	S2M04B7S
Reference	CS/ASM22009196/Ancm4 
Loss Date	16 September 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	19 Sep 2022 12:29:01 PM
Request Date	19 September 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SFK2686D
Vehicle	
Registration #	
Make	TPVD TOYOTA
Model	WISH 1.8

Service Address

, , ,

Primary Contact/Insured

ASSET LIMO
18 SIN MING LANE, #07-37 MIDVIEW CITY, 573960,
Singapore
90218889

Claim Handler

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2206420.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2022
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2022
 Resurvey Photo-3.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2022
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2022
 LKKPhotos.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2022
 SFK 2686D-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 October 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP GIA SFK2686D.pdf.pdf	Reports & Statement	GIA Report	ANG Yvonne	22 September 2022
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	19 September 2022
 INSD GIA SKB1203J.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	19 September 2022