

A.C.S. REC BY: TauferREF: CS/CT122009198/TVC

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 945K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKP8990A Yr Regn: 2014 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 116I C.C. 1598Colour: White A/C: Insured / Std / NI / NASp. Reading: 121490 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB 171712010PS 78388

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 20/9/22Survey held at Bigfoot

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Report Format: _____

Lump Sum / I.B.R. / ? _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SKP8990A

Make & Model: BMW 116

Chassis number: WBA1A12010P578388

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ bt 1,576.20
2	Bonnet lock	1	\$ x 184.40
3	Bonnet RH hinge	1	\$ x 202.00
4	Bonnet LH hinge	1	\$ x 202.00
5	Front bumper	1	\$ M 1,063.70
6	Front bumper emblem	1	\$ re 79.50
7	Front bumper emblem clips	1set	\$ re 12.00
8	Front bumper towing cover	1	\$ x 67.00
9	Front bumper RH side retainer	1	\$? 45.90
10	Front bumper LH side retainer	1	\$? 45.90
11	Front bumper inner sponge	1	\$? 55.90
12	Front bumper reinforcement	1	\$ x 465.90
13	Front bumper reinforcement garnish	1	\$ x 56.55
14	Front bumper lower beam	1	\$ x 167.40
15	Front bumper centre grille	1	\$? 178.30
16	Front bumper inner air duct rubber	1	\$? 66.00
17	Front bumper RH fog lamp garnish	1	\$ x 111.00
18	Front bumper RH fog lamp assy	1	\$ x 271.80
19	Front bumper LH fog lamp garnish	1	\$ x 111.00
20	Front bumper LH fog lamp assy	1	\$ x 271.80
21	Front bumper RH side sensor	1	\$ x 239.80
22	Front bumper RH centre sensor	1	\$ x 239.80
23	Front bumper LH centre sensor	1	\$ x 239.80
24	Front bumper LH side sensor	1	\$ x 239.80
25	Front bumper sensor rubber seal	1	\$? 44.00
26	RH headlamp assy	1	\$ cr 2,445.60
27	LH headlamp assy	1	\$ cr 2,445.60
28	Front RH grille	1	\$ cr 164.70
29	Front LH grille	1	\$ cr 164.70
30	Support panel	1	\$ x 506.70
31	Aircon condenser	1	\$ x 934.70
32	Radiator assy	1	\$ x 1,131.80
33	Front RH fender splash shield (front)	1	\$ x 66.40
34	Front RH fender splash shield (rear)	1	\$ x 125.10
35	Front LH fender splash shield (front)	1	\$ x 66.40
36	Front LH fender splash shield (rear)	1	\$ x 125.10
37	Tailgate	1	\$ bt 1,303.10
38	Tailgate "M" emblem	1	\$ re 74.20
39	Tailgate centre emblem	1	\$ re 89.20
40	Tailgate lock	1	\$? 155.70

41	Tailgate lock catch	1	\$ x 55.76
42	Tailgate inner trim board	1	\$ x 303.10
43	Tailgate weatherstrip	1	\$? 114.30
44	Tailgate wiper motor	1	\$ x 618.70
45	Rear bumper	1	\$ de 1,020.10
46	Rear bumper lower garnish	1	\$ cur 371.00
47	Rear bumper towing cover	1	\$ x 48.10
48	Rear bumper RH side reverse sensor	1	\$ x 386.70
49	Rear bumper RH centre reverse sensor	1	\$ nu 386.70
50	Rear bumper LH centre reverse sensor	1	\$ nu 386.70
51	Rear bumper LH side reverse sensor	1	\$ x 386.70
52	Rear bumper reverse sensor rubber seal	4	\$ ue 44.00
53	Rear bumper reverse sensor holders	4	\$ ue 89.40
54	Rear bumper number plate LH lamp	1	\$ x 44.40
55	Rear bumper number plate RH lamp	1	\$ x 44.40
56	Rear bumper reinforcement	1	\$? 445.60
57	Rear bumper reinforcement cover	1	\$? 81.20
58	Rear bumper RH side bracket	1	\$? 55.60
59	Rear bumper LH side bracket	1	\$? 55.60
60	End panel	1	\$? 606.72
61	End panel inner garnish	1	\$? 88.20
62	RH taillamp	1	\$? 585.30
63	RH taillamp panel	1	\$ x 178.20
64	RH taillamp lock clips	1set	\$ x 26.00
65	LH taillamp	1	\$? 585.30
66	LH taillamp panel	1	\$ x 178.20
67	LH taillamp lock clips	1set	\$ x 26.00
68	Rear fender RH inner trim board	1	\$ x 404.00
69	Rear fender RH splash shield	1	\$ x 124.00
70	Rear fender LH inner trim board	1	\$ x 404.00
71	Rear fender LH splash shield	1	\$ x 124.00
72	Rear compartment panel	1	\$ x 817.00
73	Rear compartment panel cover	1	\$? 287.00
74	Exhaust silencer	1	\$ bt 1,372.10
75	Exhaust silencer gasket	1	\$ ue 67.00

\$ 26,847.53
 Parts less 5% \$ 1,342.38
 Total \$ 25,505.15

No.	Special Nett Items	Qty	Amount S\$
1	Front number plate	1	\$ 45 80.00
2	Radiator coolant	1	\$ x 100.00
3	Front RH fender splash shield (front) clips	1	\$ x 60.00
4	Front RH fender splash shield (rear) clips	1	\$ x 60.00
5	Front LH fender splash shield (front) clips	1	\$ x 60.00
6	Front LH fender splash shield (rear) clips	1	\$ x 60.00
7	Rear fender RH inner trim board clips	1set	\$ x 80.00
8	Rear fender RH splash shield clips	1set	\$ x 40.00
9	Rear fender LH inner trim board clips	1set	\$ x 80.00
10	Rear fender LH splash shield clips	1set	\$ x 40.00
11	End panel joint sealant	1	\$? 80.00

12	End panel inner garnish clips	1set	\$ 40.00
13	LH taillamp panel joint sealant	1	\$ 30.00
14	RH taillamp panel joint sealant	1	\$ 30.00
15	Tailgate windscreen glass sealant	1	\$ 80.00
16	Tailgate windscreen glass inner seal	1	\$ 50.00
17	Tailgate sealant	1	\$ 100.00
18	Rear number plate	1	\$ 80.00
Total:			\$ 1,150.00

No.	Labour and painting	Amount S\$
	(front portion)	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,200.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 100.00
4	Apply rust coating chemical on affected areas and panels	\$ 80.00
5	Remove and reinstall aircon condenser and pipes to assist repair	\$ 250.00
6	Remove and reinstall radiator assy, hoses and fan assy to assist repair	\$ 250.00
7	Refocus and adjust headamps assy	\$ 100.00
	(rear portion)	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,600.00
2	Spray painting on affected areas and panels	\$ 1,400.00
3	Check wiring and lighting system on affected areas	\$ 120.00
4	Apply rust coating chemical on affected areas and panels	\$ 150.00
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 220.00
6	Remove and replace tailgate inner mechansim to new tailgate	\$ 180.00
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 120.00
8	Remove and replace rear inner trims and garnish to assist repair	\$ 280.00
9	Remove and replace exhaust silencer and gasket to assist repair	\$ 180.00
10	Diagnose fault code and reset	\$ 450.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Total: \$ 7,880.00

Spare Parts: \$ 25,505.15
Special Nett: \$ 1,150.00
Labour: \$ 7,880.00

Total Amount: \$ 34,535.15

Tanpin 97445749 / 62563561

WP' 20/9/27 @ 4pm

< 1/3 hrs my after repair

tanpin @ 1/4 hrs

10 days

To check consistency of accident
To check part price.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	266B

Vehicle Details

Vehicle No.:	SKP8990A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Sep 2022
Vehicle Make:	B.M.W.
Vehicle Model:	116I A/T ABS D/AIRBAG 2WD 5DR HID DSC
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	A274J773N13B16A
Chassis No.:	WBA1A12010P578388
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,541.00
Original Registration Date:	28 Aug 2014
First Registration Date:	28 Aug 2014
Transfer Count:	3
Actual ARF Paid:	\$19,158.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2024
PARF Rebate Amount:	\$10,536.00

Intended COE Rebate Details

COE Expiry Date:	27 Aug 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,001.00
COE Rebate Amount:	\$12,633.00
Total Rebate Amount:	\$23,169.00

The information contained herein is correct as at 17 Sep 2022

OK

VEHICLE NO: SLP 8990 A.

MAKE & MODEL: Bmw 116i

AUTO / MANUAL

DATE OF ACCIDENT	09 / 09 / 22.	C.C. 1.6.
TIME OF ACCIDENT	0950	AM / PM
LOCATION OF ACCIDENT	PIE (CHANGI) AFTER CT (SLE) EXIT.	
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE	
NAME OF OWNER	LIAN JUN TONG	
EMAIL	JUNTONGADONC@gmail.com	OFFICE: MOBILE: 9010 1511.
NRIC	S9315 266P.	
CLAIM TYPE	OD / THIRTY PARTY / REPORTING ONLY	
FLEET POLICY	YES / NO?	
INCURANCE CO.	NMC.	
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft	
POLICY NO.		
NAME OF DRIVER	AS ABOVE / IF NO:	
NRIC		
DATE OF BIRTH	31 / 05 / 12.	
ANY PASSENGER	YES / NO: DRIVER ONLY.	
NAME OF PASSENGER		
GENDER OF PASSENGER	MALE / FEMALE	
OCCUPATION	Outdoor / Indoor	
DATE OF DRIVING PASS	31 / 05 / 12.	
GENDER	MALE / FEMALE	
CONTACT NO.	Mobile: 90101511 Office: Home:	
EMAIL	JUNTONGADONC@gmail.com.	
ADDRESS	123 MARSLING RISE #08-100 S(730123).	
DOES DRIVER OWN OTHER VEHICLES?	NO / If yes, Reg No: INSURE: -	
RELATIONSHIP	Employee / If No: SELF.	
WEATHER CONDITION	Clear / Raining / Other:	
ROAD SURFACE	Dry / Wet / Other:	
ANY INJURIES	No / If yes, Who? DRIVER (SERIOUS).	
CONTACT NO.		
ROLICE REPORT	No / If yes, Where?	
NOTICE OF INTENDED PROSECUTION?	No / If yes, Who?	
VEHICLE B NO.	SLP 962L	Any Passenger: 1 DRIVER
NAME		UNKNOWN ANT PASSENGER.
CONTACT NO.		
VEHICLE C NO.	UNKNOWN.	Any Passenger: 1 DRIVER ONLY.
VEHICLE D NO.	GRJ 1956 J.	Any Passenger: DRIVER ONLY.
VEHICLE E NO.		Any Passenger:
VEHICLE F NO.		Any Passenger:
ANY WITNESS		
WITNESS CONTACT NO.		
WAS THERE ANY VIDEO CAPTURE?	YES / NO	
WAS THERE ANY AUDIO RECORDED?	YES / NO	
SCENE ACCIDENT PHOTOS TAKEN?	YES / NO	
WHO IS REPORTING	DRIVER / OWNER / BOTH	
Original Language Used	English / Mandarin / Others:	
Have you been approach by unknown person soliciting (s) / offering accident claims assistance?	YES / NO.	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(f) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) Investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time:

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

[illegible]

Describe Circumstance of the Accident

ON THE STATED DATE AND TIME, I CAME TO A STOP
SLOWLY BEHIND VEH D WITHOUT ANY CONTACT.
OUT OF NOWHERE, I FELT A HUGE IMPACT FROM
THE REAR AND THE IMPACT CAUSED MY VEHICLE TO BE PUSHED
FORWARD AND HIT INTO VEH D.
I WENT DOWN AND SAW THAT I WAS INVOLVED IN
A 4 CAR CHAIN COLLISION.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel