

ASS. REC. BY:

Stene

CS/AIS 22009233/LEVY3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ OD ☐ TP/WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKL 4488T Yr Regn: 28/11/20Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make: BMW 118i c.c. 1499Colour: Grey A/C: ☒ Insured ☐ Std ☐ NI ☐ NASp. Reading: 26339 T/Radio: ☒ Insured ☐ Std ☐ NI ☐ NA

Eng/No: \_\_\_\_\_

C/No: WBA 7K 3704 05R 76175Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orModl: ☒ Nil ☐ S/Rim ☐ STD A/Rim orTyre Size: F: 225/45R17R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 15/9/22 D.O.I. 20/9/22Survey held at PerformanceDes. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MK-143K

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.B.F. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

W Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 63333  
Date Estimated : 16/09/2022  
Prepared By : Yap Mee Key

Page No. : 1 of 7

### - ESTIMATE REPAIR FOR -

Lim Kian Heng (Lin Jianxing)  
Blk 291D Compassvale Street  
#14-274  
Singapore  
Singapore 544291

### - ACCOUNT - 137

Allianz Global Corporate & Specialty SE  
Singapore Branch  
12 Marina View  
Singapore 018961  
#14-01 Asia Square Tower 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4488T	WBA7K320405R76175	28/11/2020	118i	21096

DESCRIPTION	VALUE
To replace rear wheel housing, tailgate, luggage compartment, tail end panel, exhaust and attachments. <i>re-hydr - 1 x S (add rear fender LH-4 d)</i>	4259 5,950.00
To respray rear bumper, tailgate, tail end panel, trunk floor, rear wheel housing and affected areas. <i>S per (add rear fender LH)</i>	3462 3,645.00
To tow accident vehicle to PML workshop.	150.00
To supply rear emboss number plate.	78 83.00
To replace rear exhaust silencer including alignment system and conduct check for leak.	504 531.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)	504 531.00
To mount accident vehicle on culet bench or Car-O-liner to facilitate re-alignment of body / chassis accordance with BMW specification. <i>2802</i>	? 2,950.00
To replace rear windscreen glass.	545 574.00
To conduct water leak tests.	71 75.00
To supply and install rear windscreen solar film.	504 531.00
To remove and install boot compartment carpet and garnish to facilitate repair.	257 271.00
To remove and install rear seats and carpet to facilitate repair. <i>826</i>	? 870.00
To check electrical.	168 177.00
To remove old PDC assembly, replace damaged parts and	168 177.00



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 63333  
Date Estimated : 16/09/2022  
Prepared By : Yap Mee Key

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4488T	WBA7K320405R76175	28/11/2020	1181	21096

### DESCRIPTION

reconnect to new bumper including conduct check for proper function.

VALUE

To carry out body cavity preservation.  
(Per panel).2x

224 236.00

To carry out body cavity preservation.  
(For cut panel).

504 531.00

Sundries.

150.00

Total Labour 1: 17,432.00

### DESCRIPTION

QTY

PRIC

VALUE

CLIP NUT / REC	20	0.75	15.00
CLIP GREY / REC	20	1.00	20.00
C CLIP FOR PLASTIC NUT / REC	30	1.10	33.00
EXPANDING RIVET / REC	10	2.55	25.50
EXPANDING NUT / REC	2	2.85	5.70
CLIP / REC	30	3.25	97.50
SILENCER CLAMPING BUSH	1	57.70	57.70
RUBBER MOUNTING	2	18.15	36.30
MUFFLER CLAMP D=65.2MM / REC	1	44.40	44.40
TAILPIPE TRIM BRIGHT CHROME D=90MM / CUT	1	125.55	125.55
REAR SILENCER / BT	1	1,108.15	1,108.15
REAR AXLE CARRIER	1	1,609.20	1,609.20
BRACKET DWA	1	15.65	15.65
LH TRUNK LID HINGE	1	83.15	83.15
RH TRUNK LID HINGE	1	83.15	83.15
Rear left wh	1	482.30	482.30
TRUNK FLOOR	1	538.55	538.55
LH TRUNK FLOOR	1	101.25	101.25
OUTER PANEL TAIL TRIM / BR	1	390.35	390.35
INTERIOR TAIL TRIM / CR4	1	284.40	284.40
Floor panel,	1	567.50	567.50
TRUNK LID / M	1	1,257.95	1,257.95
TRUNK LID / X	1	1,257.95	1,257.95
Reinforcemen	1	106.50	106.50
Wheel arch o	1	321.55	321.55
Reinforcemen	1	51.05	51.05
REAR TRIM STRIP (LUXURY) / BR	1	126.90	126.90
REAR BUMPER LH MOUNT / BR	1	50.45	50.45
REAR BUMPER RH MOUNT / BR	1	50.45	50.45
REAR BUMPER LH SIDE GUIDE / BR	1	136.30	136.30
REAR BUMPER RH SIDE GUIDE / BR	1	136.30	136.30
REAR BUMPER CARRIER / BT	1	446.10	446.10
Protective f / REC	1	9.30	9.30

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 63333  
Date Estimated : 16/09/2022  
Prepared By : Yap Mee Key

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4488T	WBA7K320405R76175	28/11/2020	1181	21096

DESCRIPTION	QTY	PRIC	VALUE
Protective f / <i>nc</i>	1	9.30	9.30
REAR BUMPER CENTRE GUIDE / <i>BR</i>	1	163.55	163.55
REAR BUMPER TRIM PANEL (LUX PDC/PMA) / <i>BR</i>	1	1,050.55	1,050.55
REAR BUMPER TOWING EYE COVER / <i>CR4</i>	1	43.95	43.95
SET MOUNTING PDC/PMA SENSOR REAR / <i>nc</i>	1	71.60	71.60
Trim cover, ?	1	62.45	62.45
Trim cover, ?	1	62.45	62.45
LETTERING 118i / <i>nc</i>	1	65.60	65.60
GROMMET / <i>nc</i>	1	0.80	0.80
STRIKER BOOT LID X	1	50.40	50.40
BOOT LID/TAILGATE PUSH BOTTON (RFK) X	1	38.75	38.75
TRUNK LID LOCK ?	1	198.70	198.70
COUNTER SUPPORT REAR VIEW CAMERA (R) / <i>nc</i>	1	3.30	3.30
GAS PRESSURIZED SPRING F TRUNK LID ?	2	133.50	267.00
Vibration ab	1	169.95	169.95
BUMP STOP / <i>nc</i>	10	3.30	33.00
REAR WINDOW GREEN (EGS) / <i>nc</i>	1	567.15	567.15
LASHING EYE / <i>nc</i>	1	15.85	15.85
Trim panel, ?	1	144.85	144.85
REAR TRUNK TRIM PANEL ?	1	48.30	48.30
LOADING EDGE TRIM STAINLESS STEEL ?	1	184.30	184.30
TRIM PANEL TRUNK FLOOR ?	1	144.85	144.85
MOUNTING FLOOR PANEL LUGGAGE COMP. ?	1	74.80	74.80
FLOOR CARPET LUGGAGE COMPARTMENT / <i>BR</i>	1	482.85	482.85
Noise insula ?	1	84.45	84.45
Noise insula ?	1	84.45	84.45
Floor coveri ?	1	934.45	934.45
Left trunk t ?	1	144.85	144.85
Right TRUNK ?	1	144.85	144.85
Pad, side me ?	1	27.75	27.75
Pad, side me ?	1	27.75	27.75
Foam insert ?	1	22.15	22.15
Foam insert ?	1	22.15	22.15
Band clamp f ?	1	16.55	16.55
Cover, trim ?	2	16.40	32.80
HEAT INSULATION 2WD ?	1	149.00	149.00
REAR BUMPER HEAT INSULATION ?	1	62.75	62.75
Sound insula ?	1	84.45	84.45
REAR SILENCER HEAT INSULATOR ?	1	78.40	78.40
LOWER TAIL LID TRIM PANEL / <i>BR</i>	1	251.75	251.75
Sound insula ?	1	206.15	206.15
Flap, bulb e ?	1	10.55	10.55
Flap, bulb e ?	1	10.55	10.55
REAR LH WHEEL HOUSING COVER / <i>TN</i>	1	138.40	138.40
REAR RH WHEEL HOUSING COVER X	1	138.40	138.40
Undershield ?	1	81.85	81.85
PLAQUE 82MM / <i>nc</i>	1	72.85	72.85
TRUNK LID SEALING / <i>CR4</i>	1	131.25	131.25
Control unit ?	1	514.25	514.25



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 63333  
Date Estimated : 16/09/2022  
Prepared By : Yap Mee Key

Page No. : 4 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4488T	WBA7K320405R76175	28/11/2020	1181	21096

DESCRIPTION	QTY	PRIC	VALUE
Halter HKFM	1	28.50	28.50
EXPANDING NUT	30	0.55	16.50
REAR LH LIGHT IN THE SIDE PANEL	1	382.00	382.00
REAR RH LIGHT IN THE SIDE PANEL	1	382.00	382.00
REAR LH LIGHT IN TRUNK LID	1	262.15	262.15
REAR RH LIGHT IN TRUNK LID	1	262.15	262.15
REAR LH REAR REFLECTOR	1	39.80	39.80
REAR RH REAR REFLECTOR	1	39.80	39.80
REGISTRATION PLATE LAMP	1	18.20	18.20
DECOUPLING RING	4	5.30	21.20
ULTRASONIC SENSOR MINERAL GREY WB39	3	386.00	1,544.00
Absorber fun	1	49.55	49.55
Absorber fun	1	49.55	49.55
REVERSING CAMERA	1	736.50	736.50
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
Total Parts :			21,223.35

Steve CLKK)  
20/9/22, 4.00p

OD-M AL  
EXAM-?  
P/P

My BL y  
14 dgr (not include rear LH fend)  
5 dgr

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any item(s) must be resurveyed and
- No final approval from Insurance Company
- Insured by Repairer



Labour 1	:	17,432.00
Parts	:	21,223.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,705.87
Grand Total	:	41,361.22

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	15/09/2022 15:33 (SGT)
Reported by	Both
Date of Accident	15/09/2022 09:00 (SGT)
Exact Location of Accident	KPE, Singapore
Additional Location Information	KPE TOWARDS MCE BEFORE TUNNEL
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE4488T
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM KIAN HENG
NRIC No	S7320970F
Email Address	MILYDNA55@GMAIL.COM
Mobile Phone No	(Phone) +65-97321188
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	118i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1500

#### INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2000575450

#### DRIVER

Name of Driver	LIM KIAN HENG
NRIC No	S7320970F
Date Of Birth	19/06/1973
Occupation	Indoor



Valid Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

03/01/1994  
28 YEARS AND 8 MONTHS  
Male  
(Phone) +65-97321188  
-  
MILYDNA55@GMAIL.COM  
BLK 291D COMPASSVALE ST  
#14-274  
544291  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear  
Weather Conditions Clear  
Road Surface Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other vehicle or property damaged? Yes  
Number of Passengers (Including Driver) 1  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  
Translator's name -  
Translator's ID -  
Translator's phone number -  
Translator's email -  
Original language used in the statement -

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

I STOPPED MY CAR DUE TO HEAVY TRAFFIC ALONG KPE ( TOWARDS MCE), THE CAR B BEHIND HIT ONTO MY BACK.

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SNF6060R  
Vehicle Manufacturer Audi  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour Black  
Vehicle Category Private car  
Name of Driver JEROME TAN LI ZHI  
NRIC No S9918919C

Contract Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-  
-  
-



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]* 15/9/22 01335hrs

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A- SKE 4488T

B- SNF 4060T


## Describe Circumstances of the Accident

along Hwy 101 (towards MCE)

I stopped my car due to heavy traffic, the car behind hit into my back.

## Declaration

I/We declare the foregoing particulars are true in every respect.


 15/9/22 @ 13:51/3  
 Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
 Witnessed by Reporting Centre Personnel



Allianz Insurance Singapore Pte. Ltd.  
Company Registration No.: 201903913C  
GST Registration No.: 201903913C  
Address: 79 Robinson Road #09-01 Singapore 068897  
Tel: +65 6714 3369  
Website: www.allianz.sg  
Allianz Contact Centre  
Tel : 1800 222 1818 (Local)  
+65 6222 1919 (Overseas)  
Email : customerservice@allianz.com.sg



## CERTIFICATE OF INSURANCE

FORM MX1

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Certificate Number : SP2000575450-01  
Coverage : COMPREHENSIVE  
Policyholder Name : Lim Kian Heng  
Registration No. : SKE4488T  
Period of Insurance : 28 NOVEMBER 2021 to 27 NOVEMBER 2022

**Persons or Classes of Persons Entitled to Drive\*:**

- (a) The Policyholder.
- (b) Any other person who is driving on the Policyholder's order or with the his/her permission

\*Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

**Limitation as to Use\*:**

Used only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- (a) use for hire or reward
- (b) use for racing, pace-making, reliability trials or speed testing
- (c) use for the carriage of goods (other than samples) in connection with any trade or business
- (d) use for any purposes in connection with the Motor Trade

\*Limitation rendered inoperative by Section 8 of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or Amendment, Act or Acts passed in substitution thereof.

Allianz Insurance Singapore Pte. Ltd.

Hicham Raissi  
Chief Executive Officer  
Allianz Insurance Singapore Pte. Ltd.

02 October 2021  
Issued Date

Account Code : 0000103  
Excess:  
Own Damage Excess  
Windscreen Excess

SGD 0.00  
SGD 100.00