

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22009247/Uvy3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 06/10/2022	
			Code	e: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJN 446E	Veh. Inspected	SGP 9090M	
	Policy No.	P10774686R00	Coverage (\$)	0.00	
	Claim No.	C10017551/JL	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	20/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ S320L (A)	c.c	2996	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	WDD2221622A435452	Colour	SILVER	
	Odometer	35285 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/45 R19	PIRELLI	7 mm	
	L/H Front Tyre	245/45 R19	PIRELLI	7 mm	
	R/H Rear Tyre	275/40 R19	PIRELLI	7 mm	
	L/H Rear Tyre	275/40 R19	PIRELLI	7 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	13/09/2022	Inspection Date	21/09/2022	
	Survey held at	TAN LIM MOTOR PTE LTD			
		NO.1 DEFU LANE 6 SINGAPORE 539365			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: