

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIED WORLD A	SSURANCE COMPANY LTD	R	ef:	CS/AWA22009251/Ewy3m4	
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 0799	#08-01 (8th FLOOR) ON	Di	ate:	23/11/2022	
			C	ode:	AWA	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBB 7282Y	Veh. Inspected		SKR 8484J	
	Policy No.	BVFCSB0013842201	Coverage (\$)		0.00	
	Claim No.	NSV2200152/SG	Excess (\$)		0.00	
	Assign From	GOH STELLA	Assign Date		20/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA FORTE	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	KNAFZ411MF5349345	Colour		BLUE	
	Odometer	163009 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	DUNLOP		5 mm	
	L/H Front Tyre	205/55 R16	DUNLOP		5 mm	
	R/H Rear Tyre	205/55 R16	DUNLOP		5 mm	
	L/H Rear Tyre	205/55 R16	DUNLOP		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	16/09/2022	Inspection Date		01/11/2022	
	Survey held at CYCLE & CARRIAGE AUTOMOTIVE PTE LTD					
		209 PANDAN GARDENS SINGAPORE 609339				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: