

ASS. REC. BY: Pam

REF:

CS3/ASM 22009252/RVY3

358E

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 670Jat Workshop m/s WELTAC AUTO SPRAYof 60, JLO LAM HUAT #107-35/26Insured: ASM

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 48K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMJ 670J Yr Regn: 2016 JANType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda JAZZ 1.5 VTEC CVT c.c. 1498Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 08 0379 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMHK58506X201413Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 18/09/22 D.O.I. 20/09/22Survey held at WELTAC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 22KESTIMATE RANGE OF REPAIR / no. of days - (2K-3K) / 6 days

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Rep. Form(s): _____

Lump Sum / E.B. () _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	358E
Vehicle No.:	SMJ670J
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2022
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTiR CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B31020487
Chassis No.:	JHMGK5850GX201413
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,377.00
Original Registration Date:	05 Jan 2016
First Registration Date:	05 Jan 2016
Transfer Count:	2
Actual ARF Paid:	\$10,377.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jan 2026
PARF Rebate Amount:	\$6,745.00
COE Expiry Date:	04 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$18,735.00
Total Rebate Amount:	\$25,480.00

The information contained herein is correct as at 21 Sep 2022

OK

Honda Jazz 1.5A

Overview

Financial

Accessories

Similar

Research

Photos

Map



MAYFAIR
MOTORING PTE LTD



Price	\$49,800		
Depreciation ⓘ	\$13,090 /yr View models with similar depre	Reg Date	15-Feb-2016 (3yrs 4mths 24days COE left)
Mileage	81,551 km (12.4k /yr)	Manufactured ⓘ	2015
Road Tax ⓘ	\$684 /yr	Transmission	Auto
Dereg Value ⓘ	\$24,299 as of today (change)	OMV ⓘ	\$15,527
COE ⓘ	\$51,301	ARF ⓘ	\$10,527
Engine Cap	1,498 cc	Power	96.0 kW (128 bhp)
Curb Weight ⓘ	1,046 kg	No. of Owners ⓘ	3