



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009253/Acy3e2	
			Date: 12/10/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMY 6067H	Veh. Inspected	SKX 4654E
	Policy No.	D22MTPV01003799	Coverage (\$)	0.00
	Claim No.	CMTD2203336/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	20/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN X-TRAIL	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JN1JANT32Z0001297	Colour	BRONZE
	Odometer	92372 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R18	YOKOHAMA	6 mm
	L/H Front Tyre	225/60 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	225/60 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	225/60 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/09/2022	Inspection Date	20/09/2022
	Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	