

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Yr Regn: _____

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

c.c. _____

Colour: _____

A/C: Insured / Std / NI / NA

Sp. Reading _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim, or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action/Instruction

Date/Time, File Pass to?

☐ : Prelim. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.J. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

Allianz Insurance Singapore Pte. Ltd

Date : 15 Sep 2022

Attn : MOTOR CLAIMS DEPT

*Stere (LKK)
2019/02, 4.7P*

W R

L/S

*M A Y
4 dys*

ESTIMATE

VEHICLE NO. : SLT7379P
CHASSIS NO. : JM6BN22A8H0157583
MAKE / MODEL : Mazda 3
DATE OF ACCIDENT: 14 Sep 2022
YOUR INSURED VEHICLE NUMBER : SLQ96735

	PARTS DISCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	FRONT BUMPER / <i>BR</i>	1PC	\$980.00	\$980.00
2	FRONT BUMPER REINFORCEMENT <i>Xnn</i>	1PC	\$550.00	\$550.00
3	FRONT RH FENDER / <i>nn</i>	1PC	\$580.00	\$580.00
4	FRONT RH FENDER LINER / <i>CRU</i>	1PC	\$180.00	\$180.00
5	FRONT RH HEADLAMP / <i>BR</i>	1PC	\$950.00	\$950.00
6	WIPER MOTOR <i>nn</i>	1PC	\$120.00	\$120.00
7	WIPER MOTOR TANK <i>nn</i>	1PC	\$150.00	\$150.00
LIST TOTAL S\$:				\$3,510.00
20.00% DISCOUNT S\$:				\$702.00
				\$2,808.00

SPECIAL NETT

1	Bumper clips / <i>MA</i>	1 SET	\$80.00	<i>30</i>
Special Nett Total S\$:			\$80.00	

LABOUR CHARGES

1	To labour charge for removing front bumper, rh fender, front headlamp, water tank out to facilitate repairs and replacement of damage parts	\$1,000.00	<i>400</i>
2	To respray front bumper, front rh fender	\$800.00	<i>500</i>
3	To apply rustproofing on all damaged parts	\$300.00	<i>30</i>

LABOUR TOTAL S\$:	\$1,100.00
TOTAL S\$:	\$3,988.00
7% GST	\$279.16
GRAND TOTAL S\$:	\$4,267.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: