

Steve

CS/HLA22009758/Emj3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLA 13112 Yr Regn: 16/9/91  
Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Traller or

Make: BMW 216i c.c. 1499Colour: White A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 21928 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: \_\_\_\_\_

C/No: WBA 2X920907H978USGen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim, orTyre Size: F: 205/55R17R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or . \_\_\_\_\_

Front

Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 19/9/22 D.O.I. 21/9/22Survey held at PerformanceDes. of Damages ☒ Frt / ☐ Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MP-143K</u>

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: \_\_\_\_\_

1)

☐

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.F. (\$) \_\_\_\_\_

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Page No. : 1 of 6

Estimate No. : b1 63377  
Date Estimated : 20/09/2022  
Prepared By : Foong Shiuh Jye

**- ESTIMATE REPAIR FOR -**

Chan Cheng Min Serene  
87 Clover Avenue

Singapore 579359

**- ACCOUNT - 124587**

HL Assurance Pte Ltd  
11 Keppel Road  
#11-01, ABI Plaza  
Singapore 089057

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA1311Z	WBA2X920907H27845	26/02/2021	216i Active Tourer	16634

**DESCRIPTION****VALUE**

To replace bumper front panel, bonnet, front right side panel, front right door and front attachments. To repair rear right door.

4675. - 6,800.00

To spray paint bumper front panel, front right side panel, bonnet, both right doors, A pillar right.

4741 5,664.00

To replace right headlight.

486 481.00

To supply front emboss number plate.

83.00

To carry out body cavity preservation.  
(Per panel).

336 354.00

To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (1 door).

504 531.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

504 531.00

To replace wheel rim including balancing. (1x).  
\*front right

94.00

To remove and install front suspension for inspection and replace damaged parts.

2,655.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168 177.00

Sundries.

150.00

Total Labour 1: **17,520.00**



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Page No. : 2 of 6

Estimate No. : b1 63377  
Date Estimated : 20/09/2022  
Prepared By : Foong Shiuh Jye

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA1311Z	WBA2X920907H27845	26/02/2021	216i Active Tourer	16634

DESCRIPTION	QTY	PRIC	VALUE
RH WISHBONE WITH RUBBER MOUNTING	1	290.45	290.45
ALLOY RIM 7.5X17 DOUBLE SPK 549	1	977.35	977.35
HUB CAP WITH CHROME EDGE	1	31.30	31.30
FRT RH FENDER	1	639.70	639.70
BONNET	1	1,521.90	1,521.90
BONNET LH HINGE	1	115.85	115.85
BONNET RH HINGE	1	115.85	115.85
RH UPPER FRONT DOOR HINGE	1	62.95	62.95
RH LOWER FRT DOOR HINGE	1	62.95	62.95
FRT RH DOOR	1	1,130.75	1,130.75
FRT CROSSLINK	1	114.85	114.85
FRT LH BOTTOM DEFORMATION ELEMENT	1	91.60	91.60
FRT RH BOTTOM DEFORMATION ELEMENT	1	91.60	91.60
FRT BUMPER BOTTOM CARRIER	1	156.00	156.00
FRT LH TOP DEFORMATION ELEMENT	1	106.75	106.75
FRT RH TOP DEFORMATION ELEMENT	1	106.75	106.75
LH FOG LAMP SUPPORT	1	80.55	80.55
RH FOG LAMP SUPPORT	1	80.55	80.55
FRT BUMPER TOP CARRIER	1	400.80	400.80
LH FINISHER	1	50.90	50.90
RH FINISHER	1	50.90	50.90
LH MOLDING (SPORT)	1	62.55	62.55
RH MOLDING (SPORT)	1	62.55	62.55
IMPACT ABSORBER TOP	1	59.60	59.60
FRT BUMPER FLAP TOWING EYE PRIMED	1	43.95	43.95
FRT BUMPER PRIMED PANEL (PMA)	1	950.80	950.80
LH GRID LATERAL (LINES/PDC)	1	96.95	96.95
RH GRID LATERAL (LINES/PDC)	1	96.95	96.95
Grille, front left	1	114.90	114.90
Grille, front right	1	114.90	114.90
LH SUPPORT HEADLIGHT ARM	1	134.25	134.25
RH SUPPORT HEADLIGHT ARM	1	134.25	134.25
FRONT CROSSLINK	1	129.50	129.50
FRONT PANEL V STRUT	1	126.80	126.80
AIR DUCT	1	276.05	276.05
RH HEADLIGHT LED TECHNOLOGY	1	2,399.10	2,399.10
Total Parts :			11,083.40

# performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Page No. : 3 of 6

Estimate No. : b1 63377  
Date Estimated : 20/09/2022  
Prepared By : Foong Shiuh Jye

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA1311Z	WBA2X920907H27845	26/02/2021	216i Active Tourer	16634

Steve CLKK)  
21/9/22, 10.00

DD-LY AL  
EXPER-?  
P/P

by BL LY  
10 djs

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	17,520.00
Parts	:	11,083.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,002.24
Grand Total	:	30,605.64

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	19/09/2022 14:02 (SGT)
Reported by	Both
Date of Accident	19/09/2022 12:40 (SGT)
Exact Location of Accident	317 Alexandra Rd, Singapore 159965
Additional Location Information	IKEA ALEXANDRA
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA1311Z
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHAN CHENG MIN SERENE
NRIC No	S6939679H
Email Address	NUSERENE@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-91114131
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	216i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1500

### INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Policy Number / Cover Note Number	mp319661

### DRIVER

Name of Driver	CHAN CHENG MIN SERENE
NRIC No	S6939679H
Date Of Birth	13/11/1969
Occupation	Indoor



Driving Pass  
experience  
der  
ile Number  
Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

11/10/1988  
33 YEARS AND 11 MONTHS  
Female  
(Phone) +65-91114131  
-  
NUSERENE@YAHOO.COM.SG  
87 CLOVER AVE  
-  
579359  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Collided into Property  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 1  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other vehicle or property damaged? Yes  
Number of Passengers (Including Driver) 1  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  
Translator's name -  
Translator's ID -  
Translator's phone number -  
Translator's email -  
Original language used in the statement -

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number -  
Vehicle Manufacturer -  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour -  
Vehicle Category NA / Unknown  
Name of Driver -  
Contact Number -

Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-  
CAR GANTRY  
-

## SKETCH PLAN

Veh A  
Veh B


## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims  
(ii) investigating the accident and/or my claims  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


I AM AWARE THAT MY INSURER MAY HAVE A CLAIM TIME FRAME FOR ME TO SUBMIT A CLAIM AND DAMAGE CLAIM UNDER MY OWN POLICY (AND/OR CHECK MY POLICY FOR MORE DETAILS)

  
Policyholder's Signature / Date & Time

Sketch Plan

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel





Describe Circumstances of the Accident

Veh A

Veh B


I put on the "p" brake and try to insert the ticket to the ticket machine. Accidentally stepped onto the accelerator and the BMW moved forward, ramped to the side pillar of the carpark machine.


Front of car and side of car all damaged.


The IKEA gantry also damaged.

Declaration

We declare the foregoing particulars are true in every respect

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



## THE SCHEDULE

**Insured Name and Address:**  
 CHAN, CHENG MIN SERENE  
 87 CLOVER CLOVER AVENUE  
 CLOVER PARK  
 SINGAPORE 579359

**Policy No.:** MP319661  
**Period of Insurance**  
**From :** 26 Feb 2022  
**To :** 25 Feb 2023  
**(Both Dates Inclusive)**  
**Date of Issue :** 30 Dec 2021

<b>Name of Product</b>	:	Car Protect360	
<b>Scope of Cover</b>	:	Comprehensive	
<b>Registration No.</b>	:	SLA1311Z	
<b>Make &amp; Model</b>	:	BMW 216i Active Tourer	
<b>Engine No.</b>	:	31606236B38A15A	
<b>Chassis No.</b>	:	WBA2X920907H27845	
<b>Engine Capacity</b>	:	1499 c.c	
<b>Year of Registration</b>	:	2021	
<b>Sum Insured</b>	:	Market Value	<b>Windscreen</b> : Unlimited
<b>No Claim Discount</b>	:	50%	<b>Off-Peak Car</b> : No
<b>Offence Free Dis.</b>	:	Yes	<b>Vehicle Usage</b> : Private + Work
<b>NCD Protector</b>	:	No	<b>Approved Workshop</b> : No
<b>Own Damage Excess</b>	:	SGD600.00	<b>Windscreen Excess</b> : SGD100.00
<b>Y/I Driver Excess (if applicable)</b>	:	SGD3,000.00	
<b>Hire Purchase</b>	:	N/A	
<b>Authorized Drivers</b>	:	CHAN, CHENG MIN SERENE	
		N/A	
		N/A	
		N/A	
<b>Limitation as to Use</b>	:	As specified in the Certificate of Insurance	
<b>Subject to Endorsement(s)</b>	:	MAE, M02, M06, M09, M11, M13	
<b>Premium Payable</b>	:	SGD 889.32 (Inclusive of GST)	

Signed for and on behalf of  
 HL Assurance Pte. Ltd.



Authorized Signature