

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



1/38: Front View Right



2/38: Front View



3/38: Front View Left

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



4/38: Photographs of Damaged Parts



5/38: Photographs of Damaged Parts



6/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



7/38: Odometer Reading



8/38: Photographs of Damaged Parts



9/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



10/38: Photographs of Damaged Parts



11/38: Photographs of Damaged Parts



12/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



13/38: Photographs of Damaged Parts



14/38: Photographs of Damaged Parts



15/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



16/38: Photographs of Damaged Parts



17/38: Photographs of Damaged Parts



18/38: Chassis Number

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



19/38: Photographs of Damaged Parts



20/38: Photographs of Damaged Parts



21/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



22/38: Photographs of Damaged Parts



23/38: Photographs of Damaged Parts



24/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



25/38: Photographs of Damaged Parts



26/38: Photographs of Damaged Parts



27/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



28/38: Photographs of Damaged Parts



29/38: Photographs of Damaged Parts



30/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



31/38: Photographs of Damaged Parts



32/38: Photographs of Damaged Parts



33/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



34/38: Photographs of Damaged Parts



35/38: Photographs of Damaged Parts



36/38: Photographs of Damaged Parts

SKG3895Y - Submitted by: Auto Insure Pte Ltd (HQ) (Woodlands)



37/38: FRONT WHEEL TYRE SIZE AND BRAND



38/38: REAR WHEEL TYRE SIZE AND BRAND