(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC6/C1/22009282/Upa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNB 1257Z

at Workshop m/s Hire bodyshop

of

Insured:

Policy No. SLP 8456P

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $145k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1826

Vehicle: IN / OUT

Date: Person Contacted: LTA 82450

Veh No: SNB 1257Z Yr Regn: 30/07/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A) crossback

Make: Citroen DS7 c.c 1598

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 26962 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VR1J45GFU2Y050181

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: —

R: 235/55-R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm

D.O.A. 16/09/22 D.O.I. 21/09/22

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/9/22	L/S $4000 inform AH hock

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL