



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI22009294/Kvy3m4 Date: 06/10/2022 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SML 6405J	Veh. Inspected	SMV 1998U
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001246	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	21/09/2022
2. Vehicle Particulars & Condition			
Make & Model	RENAULT SCENIC (A)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	VF1RFA00362895216	Colour	METALLIC PEARL WHITE
Odometer	172256 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R20	TRIANGLE	9 mm
L/H Front Tyre	195/55 R20	TRIANGLE	9 mm
R/H Rear Tyre	195/55 R20	DAVANTI	6 mm
L/H Rear Tyre	195/55 R20	DAVANTI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/09/2022	Inspection Date	26/09/2022
Survey held at	MUNICH AUTOCARE PTE LTD 60 JALAN LAM HUAT #07-43 CARROS CENTER SINGAPORE 737869		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	