



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

20 September 2022

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SMY4271Y & SHD8591S ON 06/09/2022 @ 15:10 HRS
CARPENTER STREET

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **SMY4271Y**

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: **SHD8591S**

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **SMY4271Y** and vehicle No.: **SHD8591S** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at: **TONG LUCK AUTO PTE LTD**
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SHD8591S

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 06/09/2022

TP VEH REG NO : SHD8591S

ESTIMATE

NO : QUOT202209-000028(00)

DATE : 20/09/2022

POLICY NO : 999995730

VEH REG NO : SMY4271Y

MAKE/MODEL : MERCEDES BENZ E200 SEDAN
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130802A750123

ENGINE NO : 26492080025112

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SMY4271Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Front door - RH	1	2,240.00	2,240.00
2 Front door hinges - RH	2	170.00	340.00
3 Front RH door frame weatherstrip	1	300.00	300.00
4 Front door seal (front) RH	1	45.00	45.00
5 Front RH fender	1	1,020.00	1,020.00
6 Front RH sport rim	1	865.00	865.00
			4,810.00
		Less 10%	481.00
			4,329.00
SPECIAL NET			
7 Front door trimboard rivets RH	20	12.00	240.00
			240.00
LABOUR			
8 To remove and refit front RH door mechanism to facilitate repair	1	150.00	150.00
9 To remove and refit front RH fender to new parts	1	120.00	120.00
10 To putty and spray on the affected areas.	1	800.00	800.00
11 To check wheel alignment by computerised	1	250.00	250.00
			1,320.00
		TOTAL	S\$ 5,889.00
		ADD GST @ 7%	412.23
		GRAND TOTAL	S\$ 6,301.23

SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED ONE AND CENTS TWENTY-THREE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/09/2022 20:54 (SGT)
Reported by	Driver
Date of Accident	06/09/2022 15:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Carpenter Street
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMY4271Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXX778Z
Email Address	derrick.lee@mercedes-benz.com
Mobile Phone No	(Phone) +65-90231717
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200 SEDAN EXCLUSIVE (R18 LED)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1991

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	999995730

DRIVER

Name of Driver	SEE KIAN HENG
NRIC No	SXXXX728H
Date Of Birth	12/10/1962
Occupation	Indoor

Date Of Driving Pass	17/12/1987
Driving experience	34 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92261173
Alt. Phone Number	-
Email Address	osmarine@hotmail.com
Address	The Santorini, 25 Tampines Street 86
Address complement	#15-20
Postcode	528569
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	P1
Gender	Male

PASSENGER 2

Name	P2
Gender	Male

PASSENGER 3

Name	P3
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ALONG CARPENTER STREET ON A ONE WAY TRAFFIC MOVING SLOWLY. WHILE I WAS DRIVING, SUDDENLY 3RD PARTY SHD8591S CAME OUT FROM THE SMALL ROAD ON MY RIGHT SIDE WITHOUT CHECKING FOR THE ONCOMING TRAFFIC. HIS FRONT BUMPER COLLIDED ONTO MY FRONT RIGHT SIDE PORTION. I MANAGED TO TAKE SOME PHOTOS AND EXCHANGED PARTICULARS WITH 3RD PARTY. NO INJURIES WERE INVOLVED AT THE SCENE AND I ALSO HAVE A IN CAR CAMERA.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD8591S
Vehicle Manufacturer	Hyundai
Vehicle Model	I40
Vehicle Variant	-
Vehicle Colour	Yellow
Vehicle Category	Taxi
Name of Driver	Ang Chuak Tse
NRIC No	SXXXX540D
Contact Number	(Phone) +65-92344523
Address	Na
Address complement	Na
Postcode	Na
Insurance Company Name	-
Nature Of Damage	Na
Details of property damaged in accident	Na
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renewdate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Witnessed By Reporting Officer
Muhammad Sumardi Bin Mohd Afandi
Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan

REFER TO ATTACHED ACCIDENT DIAGRAM

Describe Circumstances of the Accident

I WAS DRIVING ALONG CARPENTER STREET ON A ONE WAY TRAFFIC MOVING SLOWLY. WHILE I WAS DRIVING, SUDDENLY 3RD PARTY SHD8591S CAME OUT FROM THE SMALL ROAD ON MY RIGHT SIDE WITHOUT CHECKING FOR THE ONCOMING TRAFFIC. HIS FRONT BUMPER COLLIDED ONTO MY FRONT RIGHT SIDE PORTION. I MANAGED TO TAKE SOME PHOTOS AND EXCHANGED PARTICULARS WITH 3RD PARTY. NO INJURIES WERE INVOLVED AT THE SCENE AND I ALSO HAVE A IN CAR CAMERA.

Declaration

(Use describe the foregoing particulars in brief as they appear)


Reporting Officer's Signature / Date & Time

Driver's Signature (If driver is not the police officer) / Date & Time

Witnessed By Reporting Officer
Muhammad Sumardi Bin Mohd Afandi
Witnessed by Reporting Officer
Name
Signature

ACCIDENT DIAGRAM

Ver. No. 2022



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Muhammad Sunami Bin Mohd Affandi
Witnessed by Reporting Centre
Personnel

AJAX MARS PTE LTD