

ASS. REC. BY:

REF: AG2 / 22009322 / Kc

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Lim Yew Boo

of 9256

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBH 8324 Y Yr Regn: 10.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Hiace c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 78775 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHH202P500245503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: TOYO 195 R15 X8

R: B.S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 20/9/22

Rear

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 4/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Est not ready

8/10 11Pm @ 3900 Cash 10/10/22 (Red. 3587.58, 48%)

Date/Time, File Pass to?

: Prel. Report

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____
S + R.S. _____

Photos

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I.: (\$ 3900)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	925G
Vehicle Details	
Vehicle No.:	GBH8324Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2827777
Chassis No.:	JTFHT02P500245503
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	12 Oct 2018
First Registration Date:	12 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$28,501.00
COE Rebate Amount:	\$17,089.00
Total Rebate Amount:	\$17,089.00

The information contained herein is correct as at 12 Oct 2022

OK

Farouweyer

SS2S229L0001 / SIN MING AUTOCARE BFG PTE LTD
ENTRY DATE & TIME: 21/09/2022 12:46 (SGT)
SUBMITTED BY: SMBFG Admin
VERSION: 1 (21/09/2022 12:46 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/09/2022 12:46 (SGT)
 Reported by Driver
 Date of Accident 20/09/2022 08:50 (SGT)
 Exact Location of Accident Aljunied Rd, Singapore
 Additional Location Information ALJUNIED ROAD SINGAPORE
 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH8324Y

INSURED/POLICYHOLDER

Is company? Yes
 Name Of Registered Owner NATUZI TRADING PTE LTD
 Company Reg No 2XXXXXX925G
 Email Address jasonphua@natuzi.com.sg
 Mobile Phone No (Phone) +65-97393352
 Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
 Model Hiace
 Variant SILVER
 Exact purpose for which vehicle was being used at time of accident -
 Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
 Vehicle Category Commercial vehicle
 Transmission Manual
 CC 2982

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited
 Policy Number / Cover Note Number 5104590842-04

DRIVER

Name of Driver YEO SONG CHIU ADRIAN
 NRIC No SXXXX522D
 Date Of Birth 10/10/1977
 Occupation Outdoor

Date Of Driving Pass	13/01/2019
Driving experience	3 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98188418
Alt. Phone Number	-
Email Address	jasonphua@natuzi.com.sg
Address	187 BISHAN STREET 13
Address complement	#07-465
Postcode	570187
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS6149Y
Vehicle Manufacturer	Kia
Vehicle Model	Cerato
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MUHAMMAD SHAFIE BIN SYED KADIR
NRIC No	SXXXX921G

Contact Number (Phone) +65-83322748
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



[Signature]
 Policyholder's Signature / Date & Time

[Signature]
 Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
 Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident

I WAS DRIVING ALONG ALJUNIGD ROAD, IT WAS RAINING. THE VEHICLE IN FRONT HAD SLOWED DOWN AND I PROCEEDED TO DO THE SAME. THE VEHICLE IN FRONT CAME TO A STOP AND I STOPPED BEHIND IT. WITHIN 1 OR 2 SECONDS I WAS HIT FROM BEHIND BY VEHICLE B.

Declaration

We declare the foregoing particulars are true in every respect.



[Handwritten Signature]

Policyholder's Signature / Date & Time

[Handwritten Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time



[Handwritten Signature]

Witnessed by Reporting Centre Personnel

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

Not Authorized
1/1 Sing & 3900/2
Resurvey After Paint
5 days

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE S' 239924

Estimate : TP22/034

Date : 20/09/2022
 Vehicle Num. : GBH 8324Y
 Make/Model : TOYOTA HIACE-2018
 Chassis/Eng# : JTFHT02P500245503/1KD2827777
 Accident Date : 20/09/2022
 Claim No. :
 Reference : LYB/GBH8324Y/AutoIns/tp/sl
 Policy No. :

Attention : Motor Claim Department
 Contact : 6221 2111

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE <i>1855.30</i>		<i>By</i> 1,855.30 ✓
2.	1	REAR TAILGATE RUBBER		<i>Sm</i> 291.20 X
3.	1	REAR TAILGATE LOCK /UPPER		<i>Trj</i> 181.20 ✓
4.	1	REAR TAILGATE LOCK / LOWER		<i>n</i> 181.20 ✓
5.	1	REAR BUMPER <i>996.40</i>		<i>By</i> 692.00 ✓
6.	1	REAR BUMPER BEAM		<i>nst</i> 295.10 X
7.	2	REAR BUMPER RETAINER	<i>Dis</i> 75.20	150.40 ✓
8.	2	REAR BUMPER FASTENER	5.00	10.00 ✓
9.	2	REAR BUMPER EXTENSION FASTENER	5.00	10.00 X
10.	2	REAR BUMPER EXTENSION GROMMET SCREW	5.00	10.00 X
11.	1	REAR TAILEND PANEL (OUTER)		<i>By</i> 398.63 ✓
12.	1	REAR TAILEND PANEL (INNER)		<i>By</i> 498.30 ✓
13.	1	REAR TAILEND PANEL TEROSTAT SEALANT		<i>na</i> 54.20 ✓
14.	1	REAR EMBLEM 'TOYOTA' IN LOGO FONT		<i>na</i> 67.80 ✓
15.	1	REAR EMBLEM 'TOYOTA'		<i>na</i> 57.70 ✓
16.	1	REAR EMBLEM 'HIACE'		<i>na</i> 47.70 ✓
List TotalS\$:				4,800.73
20% Discount S\$:				960.15
<i>256</i>				3,840.58
SPECIAL NETT ITEMS :				
1.	1	REAR '70 KM/H' STICKER		<i>na</i> 12.00 ✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE S' 239924

Attention : Motor Claim Department

Contact : 6221 2111

Estimate : TP22/034

Date : 20/09/2022
 Vehicle Num. : GBH 8324Y
 Make/Model : TOYOTA HIACE-2018
 Chassis/Eng# : JTFHT02P500245503/1KD2827777
 Accident Date : 20/09/2022
 Claim No. :
 Reference : LYB/GBH8324Y/AutoIns/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR W/SCREEN SEALANT		40.00 ✓
3.	1	REAR W/SCREEN INNER SEAL		40.00 30sl ✓
4.	1	REAR REVERSE SENSOR		250.00 200sl ✓
5.	1	REAR NO PLATE (EMBOSS)		35.00 X
Special Nett Total S\$:				377.00
LABOUR :				
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS			120.00	60sl
TO REMOVE & REFIX REAR W/SCREEN GLASS			150.00	120sl
TO TRANSFER TAILGATE PARTS & FITTING TO NEW TAILGATE			80.00	60sl
TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS			60.00	50sl
TO REMOVE,CHECK & REPAIR/REPLACE EXHAUST SILENCER			120.00	X
TO CHECK WATER LEAKAGE			60.00	20sl
TO DISMANTLE REAR INTERIOR FLOOR BOARD IN ORDER TO FACILIATE REPLACEMENT OF END PANEL & REPAIR JOB			180.00	60sl
TO REPAIR,PANEL BEAT ON REAR AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE PARTS			1,200.00	70sl

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE S' 239924

Attention : Motor Claim Department

Contact : 6221 2111

Estimate : TP22/034

Date : 20/09/2022
 Vehicle Num. : GBH 8324Y
 Make/Model : TOYOTA HIACE-2018
 Chassis/Eng# : JTFHT02P500245503/1KD2827777
 Accident Date : 20/09/2022
 Claim No. :
 Reference : LYB/GBH8324Y/AutoIns/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR TAILGATE, REAR INNER & OUTER END PANEL, LEFT & RIGHT REAR TAILLAMP LOWER PANEL, REAR BUMPER & REAR REVERSE SENSOR USING 2K PAINT		1,300.00
		Labour Total S\$:		3,270.00

700

E. & O.E.

Total S\$: 7,487.58

=====



[Handwritten Signature]

for LIM YEW BOO SPRAY PAINT CO.