


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBR 9211E
 at Workshop m/s Errat lee 03-37
 of _____
 Insured: SHC 4805J
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: FBR 9211E Yr Regn: 13/06/11
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha XT1200Z c.c. 1199
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 160823 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JYAD9011000008199
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Tyre Size: F: 110 - R0 - 19
 R: 160 - 70 - 17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: 20k.
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 17/09/22 D.O.I. 22/09/22
 Survey held at _____

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: MR Kien Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear, o/s body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
98668757
FBR 9211E 9328E 2072800
work order 12-06-2031 L7A 7016
12/10/22 1/5 @ 2300 in hand Admin girl
(Red, 7690, 77%)

Date/Time, File Pass to? : Preli. Report
 1) 14/10/22 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 2

Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
) S + RS, SI
) Photos
) Others
)
 TOTAL

Report Format :
 Lump Sum / I.B.I. (\$) 2300)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	328E
Vehicle Details	
Vehicle No.:	FBR9211E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Sep 2022
Vehicle Make:	YAMAHA
Vehicle Model:	XT1200Z
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	P401E010206
Chassis No.:	JYADP011000008199
Maximum Power Output:	-
Open Market Value:	\$16,013.00
Original Registration Date:	13 Jun 2011
First Registration Date:	13 Jun 2011
Transfer Count:	3
Actual ARF Paid:	\$2,402.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2031
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$8,043.00
COE Rebate Amount:	\$7,016.00
Total Rebate Amount:	\$7,016.00

The information contained herein is correct as at 22 Sep 2022

OK



Motorcycle Refinancing

Bike COE Renewal from 5.88% onwards for both 5/10 Years and all Motorcycle Class

Open

Bike model:
 Type Of Vehicle:
 Price From:
 Price To:
 Class:

More Search Options

Sort By:



Yamaha XT1200Z Super Tenere

Reg Date : 21/05/2011 Capacity : 1199cc
 Vehicle Type : Sport Tourers Mileage : 180000km

SGD \$16800

Posted on : 13/09/2022



Yamaha XT1200Z Super Tenere

Reg Date : 30/09/2013 Capacity : 1199cc
 Vehicle Type : Sport Tourers Mileage : 18100km

SGD \$12500

Posted on : 25/08/2022



Yamaha XT1200Z Super Tenere

Reg Date : 04/04/2014 Capacity : 1199cc
 Vehicle Type : Sport Tourers Mileage : 90754km

SGD \$13500

Posted on : 06/08/2022

[AdChoices](#)

9.9 SPECIAL
\$9,900 OFF
 OUR PETROL SUV RANGE

5008 7 SEATER CAT A SUV
 3008 AWARD WINNING CAT A SUV
 2008 PETROL SUV

Bike Gadgets

- [Number Plates for Sale](#)
- [Installment Calculator](#)
- [Instant Insurance Quote](#)

COE Results

Rd 2, 21 Sep 2022 **CAT D**
 COE Bidding of **\$11589**
 Motorcycles

Loong tired of being silent.

The big banks are scared.

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 21-Sep-22 Estimate no. 1165

Plate No. FBR9211E
Model. YAMAHA SUPER TENERE 1200

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	REAR NUMBER PLATE	\$ 30.00	hat 20 s/w	
2	REAR MADGUARD	\$ 299 450.00	re ✓	
3	REAR MADGUARD FELEETOR	\$ 60 150.00	cu ✓	
4	REAR NUMBER PLATE LIGHT	\$ 280.00	n1 X	
5	REAR BOX	\$ 500.00	su X	
6	REAR RIM ALIGNMENT	\$ 450.00	n1 X	
7	FRONT FOOTREST	\$ 220 280.00	cu ✓	
8	BRAKE PEDAL	\$ 300.00	n X	
9	EXHAUST COVER	\$ 280.00	cu ✓	
10	ENGINE CLUTH HOUSING	\$ 1,300.00	cu n/c X	
11	FUEL TANK	\$ 1,800.00	n X	
12	FRONT FENDER	\$ 750.00	n X	
13	HANDLE BAR	\$ 350 800.00	sent ✓	
14	HANDLE GRIP	\$ 380.00	n1 X	
15	HEAD LAMP BRACKET	\$ 210 300.00	sent ✓	
16	MAINSTAND	\$ 800.00	n1 X	
17	REAR RIGHT BOX	\$ 850.00	cu ✓	
18	PAINTING FUEL TANK	\$ 500.00	400	
19	LABOUR	\$ 900.00	450	

*Not Authorized
rule
mercus 90096608
22/09/22 @ 11am.
who photo after repair
3 days*

*102
4/5 @ 2300*

*P= 2269
10%
2042.1
870
2912.1
200
2321*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Paris prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Less 10% \$ 1,110.00
\$ 11,100.00
Sub Total : \$ 9,990.00
GST 7% \$ 699.30
Total: \$ 10,689.30

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*
This is computer generated no signature is required.