

369k

## Lump Sum / F.E.I.: 0%

**Add Fee:** ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

## Case Details

Case Reference Number : TAX/09/22/2038  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB5515T

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-19387-ID  
 Assigned By : Wei Siong #

Insurance Company Name : income insurance limited  
 Accident Date and Time : 18/09/2022 08:20 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

| BOM Type | Costing Type | Portion | Material Number | SMRT Recommendation          |     |                         |                |        |                       | Surveyor Approval |                   |                          |                | Remarks |
|----------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------------|-------------------|-------------------|--------------------------|----------------|---------|
|          |              |         |                 | Part Name                    | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$)       | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |         |
| Standard | Main         |         |                 | COVER, RR BUMPER ASSY        | 1   | 478.90                  | 478.90         | 25.00  | 359.17                | Replace           | 1                 | 0                        | Repair         | R       |
| Standard | Main         |         |                 | REAR BUMPER REINFORCEMENT    | 1   | 360.10                  | 360.10         | 25.00  | 270.08                | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | PAD, RR BUMPER, RH & LH, 1   | 2   | 4.30                    | 8.60           | 25.00  | 6.45                  | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | PAD, RR BUMPER, RH & LH, 2   | 2   | 4.30                    | 8.60           | 25.00  | 6.45                  | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | PAD, RR BUMPER, RH & LH, 3   | 2   | 4.30                    | 8.60           | 25.00  | 6.45                  | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | PAD, RR BUMPER, CTR          | 3   | 2.50                    | 7.50           | 25.00  | 5.63                  | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | SEAL, RR BUMPER ARM, RH & LH | 1   | 12.30                   | 12.30          | 25.00  | 9.23                  | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | STOPPER, RR BUMPER, RH & LH  | 1   | 4.80                    | 4.80           | 25.00  | 3.60                  | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | RETAINER, RR BUMPER, RH      | 1   | 127.40                  | 127.40         | 25.00  | 95.55                 | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | RETAINER, RR BUMPER, LH      | 1   | 127.40                  | 127.40         | 25.00  | 95.55                 | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | SEAL, RR BUMPER, RH          | 1   | 95.50                   | 95.50          | 25.00  | 71.63                 | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | SEAL, RR BUMPER, LH          | 1   | 95.50                   | 95.50          | 25.00  | 71.63                 | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | CLIPS PIECE, FRT & RR BUMPER | 10  | 4.80                    | 48.00          | 25.00  | 36.00                 | Replace           | 0                 | 0                        | Not Give       | Xan     |
| Standard | Main         |         |                 | GUARD, RR BUMPER, LOWER      | 1   | 623.50                  | 623.50         | 25.00  | 467.63                | Replace           | 1                 | 467.63                   | Replace        | de      |
| Standard | Main         |         |                 | FILLER, RR BUMPER, RH        | 1   | 168.60                  | 168.60         | 25.00  | 126.45                | Replace           | 0                 | 0                        | Not Give       | Xan     |
|          |              |         |                 |                              |     |                         |                |        | Total Spare Part Cost | 5,030.86          |                   |                          |                |         |
|          |              |         |                 |                              |     |                         |                |        | Lump Sum Discount (%) | 20.00             |                   |                          |                |         |
|          |              |         |                 |                              |     |                         |                |        | Final Spare Part Cost | 4,024.69          |                   |                          |                |         |
|          |              |         |                 |                              |     |                         |                |        |                       |                   | Surveyor Total    | 480.15                   |                |         |
|          |              |         |                 |                              |     |                         |                |        |                       |                   | Lump Sum Dis (%)  | 20.00                    |                |         |
|          |              |         |                 |                              |     |                         |                |        |                       |                   | Final Sur Total   | 384.12                   |                |         |

9/20/22, 2:41 PM

| SMRT Recommendation   |              |         |                 |                                         |     |                         |                |        |                 |                        | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|-----------------------------------------|-----|-------------------------|----------------|--------|-----------------|------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                               | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace        | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| Standard              | Main         |         |                 | FILLER, RR BUMPER , LH                  | 1   | 168.00                  | 168.60         | 25.00  | 126.45          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | COVER, GUARD RR BUMPER LOWER            | 1   | 16.70                   | 16.70          | 25.00  | 12.52           | Replace                | 1                 | 12.52                    | Replace        | sub     |
| Standard              | Main         |         |                 | SENSOR REVERSE                          | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | ANTENNA, ELECTRICAL KEY                 | 1   | 78.00                   | 78.00          | 25.00  | 58.50           | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | REAR BUMPER GROMMET SCREW               | 1   | 2.20                    | 1.65           | 25.00  | 1.65            | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | LENS & BODY, REAR COMBINATION LAMP , RH | 1   | 489.00                  | 489.00         | 10.00  | 440.10          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | LENS & BODY, REAR COMBINATION LAMP , LH | 1   | 489.00                  | 489.00         | 10.00  | 440.10          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | LENS & BODY ASSY , RR BUMPER , RH       | 1   | 544.40                  | 544.40         | 10.00  | 489.96          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | LENS & BODY ASSY , RR BUMPER , LH       | 1   | 544.40                  | 544.40         | 10.00  | 489.96          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | COVER, REAR COMBINATION LAMP, RH        | 1   | 69.90                   | 69.90          | 25.00  | 52.43           | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | COVER, REAR COMBINATION LAMP, LH        | 1   | 69.90                   | 69.90          | 25.00  | 52.43           | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | COVER, REAR FLOOR UNDER , RH            | 1   | 189.20                  | 189.20         | 25.00  | 141.90          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | COVER, REAR FLOOR UNDER , LH            | 1   | 261.60                  | 261.60         | 25.00  | 196.20          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | COVER, REAR FLOOR UNDER CENTER          | 1   | 249.10                  | 249.10         | 25.00  | 186.83          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Standard              | Main         |         |                 | END PANEL SUB-ASSY, BODY LOWER BACK     | 1   | 707.10                  | 707.10         | 25.00  | 530.33          | Replace                | 0                 | 0                        | Not Give       | Xm      |
| Total Spare Part Cost |              |         |                 |                                         |     |                         |                |        | 5,030.86        | Surveyor Total 480.15  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                         |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20.00 |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                         |     |                         |                |        | 4,024.69        | Final Sur Total 384.12 |                   |                          |                |         |

Labour's Cost Detail

| S.No.  | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR REAR PORTION | 676.00                  | 200.00                  |         |
| Total: |              |                        | 676.00                  | 200.00                  |         |

Spray Cost Detail


| S.No.  | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER | 378.00                  | 200.00                  |         |
| 2      | Main         | TO RESPRAY BUMPER BEAM | 180.00                  | 0                       | Xm      |
| 3      | Main         | TO RESPRAY REAR PANEL  | 180.00                  | 0                       | Xm      |
| Total: |              |                        | 738.00                  | 200.00                  |         |

**Other Cost Detail**

| S.No.  | Costing Type | Job Scope                               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-----------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO WASH AND VACUUM                      | 60.00                   | 0                       | Xm      |
| 2      | Main         | TO CHECK WIRING AND SYSTEM FUNCTION     | 120.00                  | 0                       | Xm      |
| 3      | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00                  | 0                       | Xm      |
| 4      | Main         | TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00                  | 0                       | Xm      |
| 5      | Main         | TO REPLACE SUNDRY PARTS                 | 100.00                  | 0                       | Xm      |
| Total: |              |                                         | 500.00                  | 0.00                    |         |

**Summary**

|                          | Estimator Assesment(\$) | Surveyor Assesment(\$)                                                                                                                |
|--------------------------|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------|
| Total Spare Part Detail  | 4,024.69                | 384.12                                                                                                                                |
| Total Labour Cost        | 676.00                  | 200.00                                                                                                                                |
| Total Spray Painting     | 738.00                  | 200.00                                                                                                                                |
| Other                    | 500.00                  | 0.00                                                                                                                                  |
| Overall Total            | 5,938.69                | 784.12                                                                                                                                |
| Lump Sum Repair Option   |                         | <input checked="" type="checkbox"/>                                                                                                   |
| Lump Sum Total           | 5,950.00                | 800.00                                                                                                                                |
| Surveyor Approved Amount |                         | 800.00                                                                                                                                |
| No of Repair Days*       | 4                       | 2                                                                                                                                     |
| Remarks                  | -                       | Lumpsum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9991 0089 email: rasul@lkdc.com |
| Surveyor Name            |                         | Rasul                                                                                                                                 |

| Estimator Assessment(\$) |                                                                                   | Surveyor Assessment(\$)                                                             |
|--------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Signature                |  |  |
| Survey Date              | 20/09/2022                                                                        |                                                                                     |
|                          |                                                                                   | <input type="button" value="Save"/> <input type="button" value="Clear"/>            |

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |                                              |
|---------------------------------|----------------------------------------------|
| Date of Submission              | 19/09/2022 14:59 (SGT)                       |
| Reported by                     | Driver                                       |
| Date of Accident                | 18/09/2022 16:20 (SGT)                       |
| Exact Location of Accident      | Bukit Batok West Ave. 5, Singapore           |
| Additional Location Information | BUKIT BATOK WEST AVE 5 / IN FRONT OF BLK 303 |
| Country/State of Loss           | Singapore                                    |

## DETAILS OF OWN VEHICLE

|                                                                                     |                            |
|-------------------------------------------------------------------------------------|----------------------------|
| Vehicle Registration Number                                                         | SHB5515T                   |
| INSURED/POLICYHOLDER                                                                |                            |
|  |                            |
| Is company?                                                                         | Yes                        |
| Name Of Registered Owner                                                            | Strides Taxi Pte Ltd       |
| Company Reg No                                                                      | 1XXXXX369K                 |
| Email Address                                                                       | AUTO-SVCS-TARC@SMRT.COM.SG |
| Mobile Phone No                                                                     | (Phone) +65-68662671       |
| Alternative Phone No                                                                | -                          |

### VEHICLE PARTICULARS

|                                                                              |                           |
|------------------------------------------------------------------------------|---------------------------|
| Manufacturer                                                                 | Toyota                    |
| Model                                                                        | Prius                     |
| Variant                                                                      | -                         |
| Exact purpose for which vehicle was being used at time of accident           | -                         |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category                                                             | Taxi                      |
| Transmission                                                                 | Auto                      |
| CC                                                                           | 1800                      |

### INSURANCE COMPANY

|                                   |                                |
|-----------------------------------|--------------------------------|
| Name of Insurance Company         | MS First Capital Insurance Ltd |
| Policy Number / Cover Note Number | D-22099115MFSH                 |

### DRIVER

|                |               |
|----------------|---------------|
| Name of Driver | NG SWEE TIONG |
| NRIC No        | SXXXX420J     |
| Date Of Birth  | 16/07/1975    |
| Occupation     | Outdoor       |

|                                                              |                            |
|--------------------------------------------------------------|----------------------------|
| Date Of Driving Pass                                         | 13/03/2008                 |
| Driving experience                                           | 14 YEARS AND 6 MONTHS      |
| Gender                                                       | Male                       |
| Mobile Number                                                | (Phone) +65-68662672       |
| Alt. Phone Number                                            | -                          |
| Email Address                                                | AUTO-SVCS-TARC@SMRT.COM.SG |
| Address                                                      | 11                         |
| Address complement                                           | -                          |
| Postcode                                                     | -                          |
| Is the driver the policyholder?                              | No                         |
| If No, Relationship of the Driver with the Insured           | Hirer                      |
| Does Driver Own Other Vehicles?                              | No                         |
| Vehicle Registration Number of Other Vehicle Owned by Driver | -                          |
| Insurance Company of Other Vehicle Owned by Driver           | -                          |

#### GENERAL INFORMATION OF THE ACCIDENT

|                    |                          |
|--------------------|--------------------------|
| Type of Accident   | Collision - Head to Rear |
| Weather Conditions | Clear                    |
| Road Surface       | Dry                      |

#### OTHER INFORMATION

|                                                                                                     |     |
|-----------------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in the accident?                                                   | No  |
| Number of vehicles involved in the accident                                                         | 2   |
| Was anybody injured in the Accident?                                                                | No  |
| Was any injured conveyed to hospital by ambulance?                                                  | -   |
| Was any other vehicle or property damaged?                                                          | Yes |
| Number of Passengers (Including Driver)                                                             | 2   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No  |
| Translator's name                                                                                   | -   |
| Translator's ID                                                                                     | -   |
| Translator's phone number                                                                           | -   |
| Translator's email                                                                                  | -   |
| Original language used in the statement                                                             | -   |

#### PASSENGER 1

|        |         |
|--------|---------|
| Name   | UNKNOWN |
| Gender | Male    |

#### DETAILS OF POLICE ACTION

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom?                     | -  |

#### CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG BUKIT BATOK WEST AVE 5 (INFRONT OF BLK 303) WITH ONE PASSENGER (MALE CHINESE ) ON BOARD. VEHICLES IN FRONT OF MY TAXI STOPPED AND I FOLLOWED SUIT. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SGK1917H HAD COLLIDED ONTO THE REAR OF MY TAXI.

#### ATTACHMENT(S)

|                                                   |              |
|---------------------------------------------------|--------------|
| Are accident photos available for attachment?     | Yes          |
| Was there any video captured by Car Camera?       | Yes          |
| Reasons for not uploading a video of the accident | FILE TOO BIG |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SGK1917H |
|-----------------------------|----------|

2 RF  
C

|                                         |  |               |
|-----------------------------------------|--|---------------|
| Vehicle Manufacturer                    |  | -             |
| Vehicle Model                           |  | -             |
| Vehicle Variant                         |  | -             |
| Vehicle Colour                          |  | -             |
| Vehicle Category                        |  | -             |
| Name of Driver                          |  | Private car   |
| Contact Number                          |  | TEH XIAN MING |
| Address                                 |  |               |
| Address complement                      |  |               |
| Postcode                                |  |               |
| Insurance Company Name                  |  |               |
| Nature Of Damage                        |  |               |
| Details of property damaged in accident |  |               |
| No. Of Passenger (Including Driver)     |  |               |

## SKETCH PLAN

Signat.

BIK 303

B

A

→ SGK 1917H SHBSSIST →

→ → → →

Surve

Bukit Batok West Ave 5  
 Outside BIK 303 4-20pm

18-9-22

## Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &amp; Time

Actual Driver's Signature (if driver is not the policyholder)  
/ Date & TimeWitnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

2 19-9-22

Lm. 19.9.2022

# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan

vJun2022

1

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                               |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Company                              |
| Owner ID:                     | 369K                                 |
| Vehicle No.:                  | SHB5515T                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 21 Sep 2022                          |
| Vehicle Make:                 | TOYOTA                               |
| Vehicle Model:                | PRIUS HYBRID 1.8 CVT                 |
| Primary Colour:               | Maroon                               |
| Manufacturing Year:           | 2017                                 |
| Engine No.:                   | 2ZR5098063                           |
| Chassis No.:                  | JTDKB3FU103572935                    |
| Maximum Power Output:         | 90.0 kW (120 bhp)                    |
| Open Market Value:            | \$29,007.00                          |
| Original Registration Date:   | 12 Oct 2017                          |
| First Registration Date:      | 12 Oct 2017                          |
| Transfer Count:               | 0                                    |
| Actual ARF Paid:              | \$5,000.00                           |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 11 Oct 2025                          |
| PARF Rebate Amount:           | \$3,750.00                           |
| COE Expiry Date:              | 11 Oct 2025                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 8                                    |
| PQP Paid:                     | \$34,052.00                          |
| COE Rebate Amount:            | \$13,001.00                          |
| Total Rebate Amount:          | \$16,751.00                          |

Please note that the 8-year COE for this vehicle **cannot** be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Sep 2022

OK