


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SHB 5282P
 at Workshop m/s STRINGS
 of 60, Woodmans Ind PK CV
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 5282P Yr Regn: 2017 / OCT
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA PRIUS Hybrid 1.8 CVT c.c. 1798
 Colour: MARON A/C: Insured / Std / NI / NA
 Sp. Reading: 612740 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3FU503572484
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / SR / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A. 17/09/22 D.O.I. 20/09/22
 Survey held at STRINGS
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
09/11/22	Rasul confirmed lump sum: \$1850 / 4 days (red. 6623.08, 78%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 09/11/22 ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Rep. Format: _____

Lump Sum / L.B. / 1850

Case Details

Case Reference Number : TAX/09/22/2037
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5282P

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19388-ID
 Assigned By : Wei Siong #

Insurance Company Name : income insurance limited
 Accident Date and Time : 17/09/2022 04:30 AM
 Vehicle Age(In Months) : 59

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, RR BUMPER ASSY	1	478.90	478.90	25.00	359.17	Replace	1	359.17	Replace ▾	de -
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	0	0	Check ▾	?
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace ▾	re -
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace ▾	re -
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace ▾	re -
Standard	Main			PAD, RR BUMPER, CTR	3	2.50	7.50	25.00	5.63	Replace	0	0	Not Give ▾	Xm
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	1	12.30	12.30	25.00	9.23	Replace	0	0	Not Give ▾	Xm
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give ▾	Xm
Standard	Main			RETAINER, RR BUMPER, RH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give ▾	Xm
Standard	Main			RETAINER, RR BUMPER, LH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give ▾	Xm
Standard	Main			SEAL, RR BUMPER , RH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give ▾	Xm
Standard	Main			SEAL, RR BUMPER , LH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give ▾	Xm
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace ▾	re -
Standard	Main			GUARD, RR BUMPER, LOWER	1	623.50	623.50	25.00	467.63	Replace	1	467.63	Replace ▾	de -
Standard	Main			FILLER, RR BUMPER , RH	1	168.60	168.60	25.00	126.45	Replace	0	0	Not Give ▾	Xm
Total Spare Part Cost									5,030.86	Surveyor Total		894.67		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									3,600.42	Final Sur Total		715.74		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FILLER, RR BUMPER , LH	1	168.60	168.60	25.00	126.45	Replace	0	0	Not Give	Xan
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	16.70	16.70	25.00	12.52	Replace	1	12.52	Replace	see
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	?
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	25.00	58.50	Replace	0	0	Not Give	Xan
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Give	Xan
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xan
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xan
Standard	Main			LENS & BODY ASSY , RR BUMPER , RH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xan
Standard	Main			LENS & BODY ASSY , RR BUMPER , LH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR FLOOR UNDER , LH	1	261.60	261.60	25.00	196.20	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0	Not Give	Xan
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	707.10	707.10	25.00	530.33	Replace	0	0	Not Give	Xan
Total Spare Part Cost									5,030.86	Surveyor Total		894.67		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									3,600.42	Final Sur Total		715.74		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200.00	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
2	Main	TO RESPRAY REAR PANEL	180.00	0 <i>Xm</i>	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0 <i>Xm</i>	
Total:			738.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00		request invoice
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 <i>Xm</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 <i>Xm</i>	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0 <i>Xm</i>	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00 <i>Xm</i>	
6	Main	TO WASH AND VACUUM	60.00	0 <i>Xm</i>	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Xm</i>	
Total:			852.88	336.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,600.42	715.74
Total Labour Cost	676.00	200.00
Total Spray Painting	738.00	200.00
Other	852.88	336.88
Overall Total	5,867.30	1,452.62
Lump Sum Repair Option	☐	☒
Lump Sum Total	5,850.00	1,450.00
Surveyor Approved Amount		1,450.00
No of Repair Days*	5	3
Remarks	-	Lumpsum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP :

Estimator Assesment(\$)


Surveyor Assesment(\$)

Surveyor Name

Signature



Rasul



Save

Clear

Survey Date

20/09/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/09/2022 14:21 (SGT)
Reported by	Driver
Date of Accident	17/09/2022 12:30 (SGT)
Exact Location of Accident	Near CTE, Singapore
Additional Location Information	CTE TOWARDS CITY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5282P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	STRIDES TAXI PTE LTD
Company Reg No	1XXXXXX69K
Email Address	Auto-Svcs-TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

DRIVER

Name of Driver	LAU OW PHENG
NRIC No	SXXXX303E
Date Of Birth	19/02/1964
Occupation	Outdoor

Date Of Driving Pass 21/11/2008
Driving experience 13 YEARS AND 10 MONTHS
Gender Male
Mobile Number (Phone) +65-68662672
Alt. Phone Number -
Email Address Auto-Svcs-TARC@smrt.com.sg
Address 1
Address complement -
Postcode -
Is the driver the policyholder? No
If No, Relationship of the Driver with the Insured Hirer
Does Driver Own Other Vehicles? No
Vehicle Registration Number of Other Vehicle Owned by Driver -
Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 3
Was anybody injured in the Accident? Yes
Was any injured conveyed to hospital by ambulance? No
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
Translator's name -
Translator's ID -
Translator's phone number -
Translator's email -
Original language used in the statement -

PASSENGER 1

Name UNKNOWN
Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
Police Station Name Traffic Police
Police Station Phone No (Phone) +65-65470000
Alt. Police Station Phone No (Fax) +65-65474900
Police Station Address 10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO. T/20220917/7031

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes
Reasons for not uploading a video of the accident FILE TOO BIG

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR4853D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJK1747X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LAU OW PHENG
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SHB5282P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstance of the Accident

REFER TO POLICE REPORT

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Ab 19/7/2022

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB5282P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR5095536
Chassis No.:	JTDKB3FU503572484
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	10 Oct 2017
First Registration Date:	10 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Oct 2025
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	09 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$12,978.00
Total Rebate Amount:	\$16,728.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Sep 2022

OK