

Our Job Ref No : 305530825 13.10.2022 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Date **FINALIZATION FORM** LKK Fax: Attn : **GUO QIANG** Vehicle Reg No. : SHB4019R 21.09.2022 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-Z The repair job shall bill to: EQ SMD5756U 2. The finalized amount shall be: Spare Parts after List discount (a) (b) Labour Charges Total for Part-By-Part Repair Cost Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost \$3,800.00 3. Estimated normal period for repairs: 4 working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature: ___ Name : CHIANG Name : 62148314 Date Fax : 65468156 For Official Use Only Document Confirm By Item Amount Attached Remarks (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid Ν 3. Survey Fees 4. LTA Search Fee \$7.49/\$2.00 YES

Remarks						

5. Medical Fees (on behalf of driver, if applicable)

6 Overrun