



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009351/Any3m4	
			Date: 19/04/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBQ 7371U	Veh. Inspected	SMZ 2677T
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203379/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	SUZUKI JIMNY	c.c	1462
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JSAGJB74V00166404	Colour	BLACK
	Odometer	17167 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/70 R16	GOODRICH	6 mm
	L/H Front Tyre	235/70 R16	GOODRICH	6 mm
	R/H Rear Tyre	235/70 R16	GOODRICH	6 mm
	L/H Rear Tyre	235/70 R16	GOODRICH	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/09/2022	Inspection Date	22/09/2022
	Survey held at	FONG MOTORS 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	