



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref:	CS3/ASM22006835/Gcy3m4-1
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	19/10/2022
ATTN: HO WINNIE			Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SHA 3499A	Veh. Inspected	SJR 42R	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M046UY	Excess (\$)	0.00	
Assign From	HO WINNIE	Assign Date	22/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC 1.5 TURBO	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MRHFC1660HT000473	Colour	YELLOW	
Odometer	79638 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 ZR18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/40 ZR18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/40 ZR18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/40 ZR18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	16/07/2022	Inspection Date	05/10/2022	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	