

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22006835/Gcy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	17/08/2022		
	ATTN: HO WINNIE			Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 3499A	Veh. Inspected	l	SJR 42R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M046UY	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		19/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CIVIC 1.5 TURBO	c.c		1498	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MRHFC1660HT000473	Colour		WHITE	
	Odometer	78077 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/40 ZR18	BRIDGESTONE		6 mm	
	L/H Front Tyre	235/40 ZR18	BRIDGESTONE		6 mm	
	R/H Rear Tyre	235/40 ZR18	BRIDGESTONE		6 mm	
	L/H Rear Tyre	235/40 ZR18	BRIDGESTONE		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
5.	General Information					
	Accident Date	16/07/2022	Inspect Date /	Time	19/07/2022 (03:30 PM)	
	Survey held at	BLUWEL AUTOMOTIVE SERVIO	CE PL			
		BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883)			
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000					
5b.		Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					
		Depart Def No. CCO/A	01.1000000000000			

Report Ref No. CS3/ASM22006835/Gcy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.