

ASS. REC. BY:

REF: NS/INC22009365/Rvc

369K

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 6228Eat Workshop m/s STRINGSof 60 motorways Ltd Rk 64Insured: SDG 9298P INC

Policy No. \_\_\_\_\_


Claims No. MT/1189573-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 6228E Yr Regn: 2016 / MAYType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS TAXI (SAR) c.c. 1798Colour: MAROON A/C: Insured / Std / NI / NASp. Reading: 491124 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKN36U205767969Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SAILUN

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20/09/22 D.O.I. 22/09/22Survey held at STRINGSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/11/22 Rasul informed LS \$1250 (red 8944.70. 87%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 8/11/22-typist

Rep. Form: TP

Lump Sum / F.B.: \$1250

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$ \_\_\_\_\_

Photos

Others

TOTAL



## Case Details

Case Reference Number : TAX/09/22/2045  
Type of Repair : Accident Repair  
Vehicle Registration Number : SHD6228E

Company Type : Strides Taxi Pte Ltd  
Estimation ID : EST-19413-ID  
Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited  
Accident Date and Time : 20/09/2022 09:30 AM  
Vehicle Age(In Months) : -

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
Standard	Main			BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	10	18.00	Replace ▾	na	
One Time Key In	Main			BUMPER REAR	1	478.90	478.90	25.00	359.17	Replace	1	359.1	Replace ▾	de	
Standard	Main			BUMPER REINFORCEMENT REAR	1	234.70	234.70	25.00	176.02	Replace	0	0	Check ▾	?	
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check ▾	?	
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check ▾	?	
Standard	Main			ANTENNA,ELECTRICAL LOWER REAR	1	208.10	208.10	10.00	187.29	Replace	0	0	Check ▾	?	
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check ▾	?	
Standard	Main			BUMPER SIDE RETAINER RR/LH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give ▾	yan	
Standard	Main			BUMPER SIDE RETAINER RR/RH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give ▾	yan	
Standard	Main			BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give ▾	yan	
Standard	Main			BUMPER SEAL, RR RH	1	74.40	74.40	25.00	55.80	Replace	0	0	Not Give ▾	yan	
Standard	Main			BUMPER LIP COVER RR/LH	1	93.90	Total Spare Part Cost 5,008.22 93.90	25.00	70.43	Replace	0	Surveyor Total 0	377.17	Not Give ▾	yan
Standard	Main			BUMPER LIP COVER RR/RH	1	155.40	Lump Sum Discount (%) 20.00 155.40	25.00	116.55	Replace	0	Lump Sum Dis (%) 20	20	Not Give ▾	yan
						Final Spare Part Cost	4,006.58			Final Sur Total		0	Not Give ▾	yan	

Standard	Main	Portion	Material	Part Name	Qty	List	List	Dis(%)	Final	Repair/	Surveyor	Surveyor	Approval	Remarks
BOM	Costing	Type	Number			Price	Price		Price	Replace	Quantity	Final	Not Give	
Standard	Main					Per	(\$)		(\$)	Replace	0	Price(\$)	Repair/Replace	
						Unit(\$)							Not Give	
Standard	Main			END PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Check	?
Standard	Main			TAILGATE ASY	1	1,260.70	1,260.70	25.00	945.53	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE DOOR LOCK	1	631.90	631.90	10.00	568.71	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE LOCK, COVER	1	20.70	20.70	25.00	15.52	Replace	0	0	Not Give	Xm
Standard	Main			STRIKER, BACK DOOR	1	55.80	55.80	25.00	41.85	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE DOOR WEATHER STRIP	1	402.50	402.50	25.00	301.88	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE OUTSIDE GARNISH	1	574.80	574.80	25.00	431.10	Replace	0	0	Not Give	Xm
Standard	Main			EMBLEM REAR	1	68.70	68.70	25.00	51.53	Replace	0	0	Not Give	Xm
Standard	Main			NAME PLATE (HYBRID)	1	59.20	59.20	25.00	44.40	Replace	0	0	Not Give	Xm
Standard	Main			NAME PLATE (PRUIS)	1	69.40	69.40	25.00	52.05	Replace	0	0	Not Give	Xm
Standard	Main			NAME PLATE (TOYOTA)	1	59.20	59.20	25.00	44.40	Replace	0	0	Not Give	Xm
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xm
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xm
Total Spare Part Cost											Surveyor Total		377.17	
Lump Sum Discount (%)										20.00	Lump Sum Dis (%)		20	
Final Spare Part Cost										4,006.58	Final Sur Total		301.74	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	200	
Total:			1,014.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	0	Xm
3	Main	TO RESPRAY BUMPER BEAM	150.00	0	Xm
4	Main	TO RESPRAY TAIL GATE	378.00	0	Xm
Total:			1,296.00	200.00	



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0 Xnn	
Total:			1,296.00	200.00	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 Xnn	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 Xnn	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 Xnn	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 Xnn	
Total:			500.00	40.00	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,006.58	301.74
Total Labour Cost	1,014.00	200.00
Total Spray Painting	1,296.00	200.00
Other	500.00	40.00
Overall Total	6,816.58	741.74
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	6,800.00	750.00
Surveyor Approved Amount		750.00
No of Repair Days*	6	2
Remarks		

Surveyor Name

Signature:

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

REQ NBV / Lumpsum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR  
RASHU : 0904 0069 email: rashu@lkkauto.com

Rasul



Save

Clear

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	22/09/2022 12:33 (SGT)
Reported by	Driver
Date of Accident	20/09/2022 17:30 (SGT)
Exact Location of Accident	Portstown Ave, Singapore
Additional Location Information	SLIP ROAD TOWARDS PORTSDOWN AVENUE
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6228E
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

## INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

## DRIVER

Name of Driver	TANI TAN TECK THYE
NRIC No	SXXXX090C
Date Of Birth	22/07/1966
Occupation	Outdoor

Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Name of Driver  
Contact No

Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

01/12/1987  
34 YEARS AND 9 MONTHS  
Male  
(Phone) +65-68662672  
-  
AUTO-SVCS-TARC@SMRT.COM.SG  
11  
-  
-  
No  
Hirer  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Collision - Head to Rear  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other vehicle or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  
Translator's name  
Translator's ID  
Translator's phone number  
Translator's email  
Original language used in the statement

No  
2  
No  
-  
Yes  
2  
No  
-  
-  
-  
-

#### PASSENGER 1

Name  
Gender

UNKNOWN  
Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Was notice of intended Prosecution given?  
If yes, against whom?

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

WHILE I WAS STATIONARY AT THE SLIP RD OF PORTSDOWN AVE SUDDENLY THE VEHICLE SDG9298P COLLIDED ONTO THE REAR PORTION OF MY VEHICLE. 1 PAX INSIDE THE TAXI.

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Reasons for not uploading a video of the accident

Yes  
Yes  
FILE TOO BIG

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number  
Vehicle Manufacturer

SDG9298P  
-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	AUTO-SVCS-TARC@SMRT.COM.SG
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan





Describe Circumstance of the Accident

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature/Date & Time

Driver's Signature (if different from policyholder)/Date & Time

Witnessed by Third Party Centre (if witness Numbered in NR2017 (para))

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHD6228E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6593384
Chassis No.:	JTDKN36U205767969
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	13 May 2016
First Registration Date:	13 May 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 May 2024
PARF Rebate Amount:	\$3,250.00
COE Expiry Date:	12 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,463.00
COE Rebate Amount:	\$7,452.00
Total Rebate Amount:	\$10,702.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Sep 2022

OK