



Your Ref: S9M0251X

Date: 14th Dec 2022

Our Ref: CS3/ASM19019224/Ccy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Chong Arnold

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLR 3490L

INSURED VEHICLE: SMG 5358U

ACCIDENT DATE: 26/10/2019

We thank you for your instruction on 22/09/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLR 3490L from M/s Prominent Appraiser Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLR 3490L and SJN 7362S.
- c) Police report of Vehicles SLR 3490L.
- d) Final Repair Bill of SLR 3490L from M/s My Car Consultant Pte Ltd.
- e) Colour damaged vehicle photographs of SLR 3490L.

Pre-Repair Inspection Date: 31/10/2019 at M/s My Car Consultant Pte Ltd, 53 Ubi Avenue 1 #01-33 Paya Ubi Industrial Park, Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLR 3490L
Make & Model	: Toyota C-HR Hybrid 1.8G CVT
Year of Registration	: 2017
Chassis Number	: ZYX102042426
Engine Capacity	: 1797 cc

2. We recommend that the repairs of the entire damage require about 18 (Eighteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.