

ASS. REC. BY:

REF: AIS/ CS/AIS22009384/Kvy3Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. SPCM1000000913Claims No. 202222006681SL


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$92k without Refrigerator

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 07 days

Res.: Yes or No

Lum Sum: 18120 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: YQ 3990LYr Regn: 051 21Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MSYCarter

c.c

2998Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 40736

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

FEB 71 EA 30141Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

215/75R17.5(D)BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 11/9/22D.O.I. 23/9/2022

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/5/23

Kenneth confirmed final fig \$8345.60 (Red 1204.50, 13%)

Data/Time, File Pass to?



: Prell. Report

1)



: Final Report

Data/Time, File Return to?

2) 9/5/23-typist

Days Of Repair: 7Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$




Tech Invs (\$



Weekend (\$

Report Format: Merimen

Lump Sum / I.B.I. (\$ 8345.60)



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD ALLIANZ
Policy No:	SPCM1000000913	Date of Loss:	11/09/2022
Vehicle Reg. No.:	YQ3990L	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MANDAI LINK LOGISTICS PTE LTD		
Driver:	HII PENG LEE		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) (M)	Vehicle Reg. Date:	27/05/2021
Vehicle Colour:	WHITE	Chassis No:	FEB71EA30141
Engine No:	4P10D82592		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		

*Not Authorized
Runny B & paint
Ex @ 900k*

Present Location: CHENG HOE MOTOR PTE LTD (WOODLANDS)

Today

COST OF CLAIMS

	Amount
Parts	6,806.80
Miscellaneous Items	20.00
Labour	2,280.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,106.80
+ GST 7.00% (S\$)	637.48
Nett Amount (S\$)	9,744.28

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Sep 2022)
 Parts: N/A MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database) *Met*
 Labour: Repairer's (Price-denominated Standard List) *Canter*
 Print Code: Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	0.00	0.00	*490.00 F
2	1		*1 PC FRT BUMPER LH SIDE PAD	0.00	0.00	*180.00 F
3	1		*1 PC FRT BUMPER LH BRACKET	0.00	0.00	*98.00 F
4	1		*1 PC FRT BUMPER LH STAY	0.00	0.00	*85.00 F
5	1		*1 PC FRT BUMPER RH BRACKET	0.00	0.00	*98.00 F
6	1		*1 PC FRT GRILLE	0.00	0.00	*550.00 F
7	1		*1 SET FRT GRILLE CLIP	0.00	0.00	*24.00 F
8	1		*1 PC LH SIGNAL LAMP	0.00	0.00	*150.00 F
9	1		*1 PC LH HEADLAMP	0.00	0.00	*280.00 F
10	1		*1 PC FRT LH CORNAL GARNISH	0.00	0.00	*120.00 F
11	1		*1 PC FRT PANEL	0.00	0.00	*520.00 F
12	1		*1 PC FRT WIPER GARNISH	0.00	0.00	*195.00 F
13	1		*1 PC FRT WINDSCREEN RUBBER	0.00	0.00	*200.00 F
14	1		*1 PC FRT LH SIDE MIRROR ROUND	0.00	0.00	*45.00 F
15	1		*1 PC FRT LH SIDE MIRROR SQUARE BACK COVER	0.00	0.00	*28.00 F
16	1		*1 PC AIRCON EVAPORATOR	0.00	0.00	*1,650.00 F
17	1		*1 PC CABIN FRT LH MOUNTING	0.00	0.00	*395.00 F
18	1		*1 PC CABIN FRT MOUNTIN CROSS BAR	0.00	0.00	*380.00 F
19	1		*1 SET AIRCON HEATER PIPE	0.00	0.00	*160.00 F
20	1		*1 PC HORN	0.00	0.00	*55.00 F
21	1		*1 PC AIRCON GAS DISCHARGE HOSE	0.00	0.00	*150.00 F
22	1		*1 PC AIRCON GAS RECEIVER HOSE	0.00	0.00	*165.00 F
23	1		*1 PC BRAKE OIL PIPE	0.00	0.00	*170.00 F

F=Franchise part.

Sub Total (\$\$) 6,188.00
 + Margin on L,N Items 10.00% (\$\$) 618.80
 Total Parts (\$\$) 6,806.80

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.
 Generated using Merlmen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC FRT NO. PLATE	
2	1	1 PC FRT NO. PLATE	20.00
Sub Total (\$\$)			20.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.
 Generated using Merlmen e-Claims IEAS

No	Particulars	Lab.Type	Amount
Labour Items			
1	1) TO REMOVE AND REFIX FRT WINDSCREEN GLASS	New	100.00 ✓
2	2) TO REMOVE AND REFIX AIRCON, CHECK, VACUUM AND REFILL GAS	New	100.00 ✓
3	3) TO REMOVE AND REFIX DASH BAORD, METER ASSY AND CHECK WIRING	New	280.00 25
4	4) TO PANEL BEATING INCLUDE STRAIGHTEN FRT LH WS PILLAR AND RE-ALIGN CABIN POSITION	New	Pool 1,000.00
5	5) TO PUTTY AND RESPRAY ON FRT PANEL, FRT CORNAL PANEL, FRT GRILLE, BUMPER, BRACKET , FRT LH WS PILLAR	New	Pool 800.00

Gross Labour Cost (\$\$) **2,280.00**

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

YQ3990L
0D/A1/2022

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 873W

Vehicle Details

Vehicle No.: YQ3990L
Vehicle to be Exported: Yes
Intended Deregistration Date: 21 Sep 2022
Vehicle Make: MITSUBISHI
Vehicle Model: CANTER FEB71ER3SDEN (CBU)
Primary Colour: White
Manufacturing Year: 2020
Engine No.: 4P10D82592
Chassis No.: FEB71EA30141
Maximum Power Output: -
Open Market Value: \$41,886.00
Original Registration Date: 27 May 2021
First Registration Date: 27 May 2021
Transfer Count: 0
Actual ARF Paid: \$2,095.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 May 2031
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$25,959.00
COE Rebate Amount: \$20,767.00
Total Rebate Amount: \$20,767.00

The information contained herein is correct as at 21 Sep 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/09/2022 15:21 (SGT)
Reported by Driver
Date of Accident 11/09/2022 17:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information AYE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YQ3990L

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner MANDAI LINK LOGISTICS PTE.LTD
Company Reg No 2XXXXX873W
Email Address elaine@pincorpn.com.sg
Mobile Phone No (Phone) +65-67558758
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model CANTER FEB71ER3SDEN (CBU)
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Manual
CC 2998

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number SPCM1000000913

DRIVER


Name of Driver HII PENG LEE
Passport No/FIN GXXXX612R
Date Of Birth 28/06/1971
Occupation Outdoor

Describe Circumstance of the Accident

**** NOTE : PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.**

() Claim Own Policy () Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan



Doc: 11/9/22

Time: 1730hrs.

Ins: Allianz

While filtering to lane 2, I did not realize m/van (B) had slowed down - my vehicle accidentally collided onto the van rear portion.

No injuries on anyone - I was driving alone. Clear, dry weather condition.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

[Signature] 12/9/22 (YS)